

**BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 10305.000889  
QUAD \_\_\_\_\_  
SERIES \_\_\_\_\_  
NEG. NO. \_\_\_\_\_

Form 10

YOUR NAME: B. Van Liew, Consultant/WHC DATE: 5/6/83

YOUR ADDRESS: Box 416, St. James, L.I. 11780 TELEPHONE: 516-584-5600

ORGANIZATION (if any): \_\_\_\_\_

\*\*\*\*\*

**IDENTIFICATION**

- 1. BUILDING NAME(S): Building 46-Viele Building
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Central Islip
- 3. STREET LOCATION: east side of Carleton Ave.
- 4. OWNERSHIP: a. public  b. private
- 5. PRESENT OWNER: New York State ADDRESS: \_\_\_\_\_
- 6. USE: Original: \_\_\_\_\_ Present: vacant
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes  No   
Interior accessible: Explain \_\_\_\_\_

**DESCRIPTION**

- 8. BUILDING MATERIAL: a. clapboard  b. stone  c. brick  d. board and batten   
e. cobblestone  f. shingles  g. stucco  other: \_\_\_\_\_
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints   
b. wood frame with light members   
c. masonry load bearing walls   
d. metal (explain) \_\_\_\_\_  
e. other \_\_\_\_\_
- 10. CONDITION: a. excellent  b. good  c. fair  d. deteriorated
- 11. INTEGRITY: a. original site  b. moved  if so, when? \_\_\_\_\_  
c. list major alterations and dates (if known):


vacant & vandalized . TOP FLOOR BURNED IN EARLY 1930'S . NEW ROOF ELIMINATED THAT FLOOR.

12. PHOTO: CI-WHC-r-1,30 from SW

13. MAP: NYS DOT-Bayshore Quad



HP-1



14. THREATS TO BUILDING: a. none known  b. zoning  c. roads   
 d. developers  e. deterioration   
 f. other: \_\_\_\_\_

15. RELATED OUTBUILDINGS AND PROPERTY:  
 a. barn  b. carriage house  c. garage   
 d. privy  e. shed  f. greenhouse   
 g. shop  h. gardens   
 i. landscape features: \_\_\_\_\_  
 j. other: \_\_\_\_\_

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  
 a. open land  b. woodland   
 c. scattered buildings   
 d. densely built-up  e. commercial   
 f. industrial  g. residential   
 h. other: \_\_\_\_\_

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
 (Indicate if building or structure is in an historic district)

The building is located on the east side of Carleton Ave.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

The top floor burned in the early 30's and was replaced by present roof.

**SIGNIFICANCE**

19. DATE OF INITIAL CONSTRUCTION: 1909

ARCHITECT: \_\_\_\_\_

BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The building is a large 2 story, E-shaped brick structure, slate hip roof with omega dormers. Double deck, flat roof porches with gothic style wood spandrels on east end of center wing and north and south elevations of end wings. Slightly projecting 3 bay entrance unit on west.

21. SOURCES:

Atlas of the Ocean Shore of Suffolk Co. (westerly section)  
 N.Y.: E. Belcher Hyde, 1915, Plate 6

22. THEME: