BUILDING-STRUCTURE INVENTORY FORM


		机械 医直角操作法 化		N. 1987		Jan 2018		3013
FOR (OFFICE U	SE ONLY						
				1				
LINIO	UE SITE N	いんのくつ	55-105	14 11	卫	0a	. 29	
OTTAL		'u. <u>u</u>						
QUAL	100 000 000 000 000					gr	een	
SERIE	And the second of the second							
NEG.	NO					770	110	W
						y -	الله ملت بنات	**


	TORIC PRESERVATION PARKS AND RECREATION RK (518) 474-0479	QUAD	
YOUR NAME	Town of Islip Town 655 Main Street	Hall DATE:	5/23/79
YOUR ADDRI	ESS: Islip, N.Y.	TELEPHONE:_	(516) 224-5450
	ON (if any): Department of		
* * * * * * * *	* * * * * * * * * * * * * * * * * * *	* * * * * * *	* * * * * * *
IDENTIFICATION	Vanderbilt Chicker		
1. BUILDING NAM		나는 바로 가지 않는데 얼마를 하는데 없다.	한 발생이 되지나 말했다. 그는 생기가 하였다.
2. COUNTY:	Suffolk TOWN/CITY:	TRTTD AILI	AGE: Oakdare
3. STREET LOCAT	ION: 4 Jade Street		
4. OWNERSHIP:	a. public 🔲 b private 🗷		# *
5. PRESENT OWNE	R: Bunting A Chicken coop Pr	DDRESS: See	72
6. USE: Original:	cnicken coop Pi	resent: <u>reside</u>	
7. ACCESSIBILITY	TO PUBLIC: Exterior visible from Interior accessible:	m public road: Yes Explain	No L
DESCRIPTION			
8. BUILDING MATERIAL:	a. clapboard b. stone c. cobblestone f. shingles	c. brick □ c □ g. stucco □ o	l. board and batten 🗆 ther:
9. STRUCTURAL	그 그 그 그 그 이 그는 생각으로 그리고 그 그러 있는 그릇 생각을 하고 있다면 살아가는 그는 그 이렇다면 묶어.		
SYSTEM:	b. wood frame with light member		
(if known)	c. masonry load bearing walls 🗷		
	d. metal (explain)		
	e. other	<u> </u>	
	a. excellent 🗆 _ b. good 🛣 _ c.		
	a. original site 🗆 🔻 b. moved 🗔		
	c. list major alterations and dates (if k	(nown):	

12. PHOTO: Neg. 18, east facade NJM-1

13. MAP:

Bowe-Anderson Composite







14.	THREATS TO BUILDING: a. none known d. developers □ e. deterioration □ f. other:
	RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage c. d. privy c. e. shed c. f. greenhouse c. garage c.
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other: similar buildings in farm complex
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
	Northwest corner of Jade Street and Featherbed Lane, in the historic Artist Colony.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	2 story brick structure with gable roof. Vent survives on roof of 1 story portion.
<u>SIC</u> 19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: 1890
	ARCHITECT:
	BUILDER: William Bason and Sons
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE: This building was part of the farm area of the Vanderbilt estate. In 1926, this area was purchased by Lucy Sawyer Pritchard Thompson and her son, William, turning it into the Artist Colony, a haven for many New York City Artists.

21. SOURCES: Ari L. Goodman, "Preservation, Restoration, Consternation," New York Times, June 20, 1976.

Jack Stein, "Cooped Up in a Historic Community," Suffolk Life,
May 25, 1977.

22. THEME:
Prepared by: Society for the Preservation of Long Island Antiquities
Setauket, New York 11733
Nina Monastero, Research Assistant
May, 1979