## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR C	OFFICE USE ONLY
	103 00 0759-0-
	je site no. <u>103-05-</u> 0359-07
QUAD SERIE	물론 중 1995년 1
NEG. I	선생물 중요한 경기를 가면 하면 살을 하는 것이다. 그런 그 그런 그는 그는 그를 하는 것이다.
111111	NY)

0a 2 green red

그러 집에도 어느 함께 있는데 그렇지 않다고 다니?	일으로 마시 점점 그가 이렇게 되었다. 일을 들고려를 받아 된 것으로 살았다. 다음		
YOUR NAME	3: Town of Islip	DATE:	5/18/79
YOUR ADDF	655 Main Street	TELEPHONE:	<b>(516)</b> 224 <b>-</b> 5450
ORGANIZAT	ION (if any): Department of	Planning and	Development
* * * * * * * IDENTIFICATION I BUILDING NAM	* * * * * * Vanderbilt And (E(S) East Gatehouse	그렇게 하는 것이 되었다면 하나는 사람들이 살아가 나를 보고 있다. 나는 하는 점점	* * * * * * *
COUNTY: St	IE(S): East Gatehouse IIIfolk TOWN/CITY: TOWN/CITY:	Islip VILI	AGE: Oakdale
. STREET LOCA	rion: Vanderbit Blud; ec	For Side; South o	of Montank lerbi
. OWNERSHIP:	a. public 🗆 b. private 🔼 FR Rousseau & Sadowski	ADDRESS See #	3 Hwy
. USE: Original:	Gatehouse	Present: Beauty	Salon
	TO PUBLIC: Exterior visible fr	rom public road: Yes [ le: Explain <u>Reta</u>	x No 🗆
ESCRIPTION			
BUILDING MATERIAL:	a. clapboard ☐ b. stone ☐ e. cobblestone ☐ f. shingles		
STRUCTURAL SYSTEM: (if known)	[20] - [20] [20] - 전문	ibers 🗷	
. CONDITION:	e. other  a. excellent  b. good  o		iorated 🗆

a. original site 🖾 b. moved 🗀 if so, when?

c. list major alterations and dates (if known):


Neg. 3, West facade 12. PHOTO: NJM-1

11. INTEGRITY:

13. MAP:

Bowe-Albertson Composite








14.	THREATS TO BUILDING: a. none known  b. zoning  c. roads  d. developers  e. deterioration  f. other:	
	RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house c. garage d.  d. privy e. shed f. greenhouse g. shop h. gardens i. landscape features:  i. other:	
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up  se. commercial  fr. industrial  g. residential  h. other:	
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)  Situated at the Southeast corner of Montauk Hwy. and Vanderbilt Blvd., the east Gatehouse marks the eastern Entrance to what was once the estate of William K. Vanderbilt.	
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):	
	2 story English style cottage, with which the original stoop survives. The exterior is composed of a smooth brick first floor. All windows are diamon pane easements.	
CICI	NIFICANCE hofone 1909	
	NIFICANCE DATE OF INITIAL CONSTRUCTION:  Defore 1888	
	ARCHITECT: Richard Morris Hunt	
	BUILDER:	
20.	영화 (148) 후, 호, 하, 14 (14) 개호, 14 (14) 14 (14) 14 (14) 14 (14) 14 (14) 14 (14) 14 (14) 14 (14) 14 (14) 14 (14)	
	The East Gatehouse is a well-survived example of the 19th century architecture of the Vanderbilt estate. It cost \$40,000 when erected. The iron and stone fence and entrance gates were installed in 1890.	
l 22.	SOURCES: *W. K. Vanderbilt Historical Society Merritt B. Hyde, Atlas of a Part of Suffolk County, Long Island, N.Y. South Shore, Ocean Side. E. Belcher Hyde, Brooklyn, N.Y. Ruth Doughtery, "Reflections of the Past." Suffolk County News THEME: April 4, 1974 epared by: Society for the Preservation of Long Island Antiquitle Setauket, New York 11733 Nina Monastero, Research Assistant	
	May, 1979	

## W.K. Vanderbilt East Gate House Idle Hour



This original W. K. Vanderbilt building, erected in 1889 at a cost of \$40,000, was the fifty mile mark from New York where the bicycle "Century Runs" of yesterday would stop to take a drink from the Vanderbilt well on the highway, sign the guest books kept at the lodge, and take the return journey back to the city.

1973 Series

W. K. Vanderbilt Historical Society