## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

| FOR OFFICE USE ONLY |        |
|---------------------|--------|
| UNIQUE SITE NO      | Quad I |
| SERIES              | No. 23 |
| NEG. NO.            |        |

393-02-65 then 691


|            | (310) 4740477 | NEG. NO.                 |
|------------|---------------|--------------------------|
| YOUR NAME: | Town of Islip | DATE: September 26, 1975 |
|            | Town Hall     |                          |

YOUR ADDRESS: 655 Main Street TELEPHONE: (516) 581-2000


ORGANIZATION (if any): Department of Planning, Housing & Development

| IDENTIFICATION CONTRACTOR NAME OF THE PARTY |
|---|
| 1. BUILDING NAME(S): Group of five Victorian houses on Park Avenue  |
| 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Bay Shore  |
| 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Bay Shore 3. STREET LOCATION: #42, #46, #48, #50, and #52 Park Avenue (west side)  |
| 4. OWNERSHIP: a. public  b. private  \bar{\times}   |
| 5. PRESENT OWNER: ADDRESS:  |
| 5. PRESENT OWNER: ADDRESS: 6. USE: Original: Residences Present: Residences   |
| 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: les X No \( \square\)  |
| Interior accessible: Explain By appointment only  |
| DESCRIPTION   |
| 8. BUILDING a. clapboard b. stone c. brick d. board and batten  |
| MATERIAL: e. cobblestone □ f. shingles □ g. stucco □ other: varied  |
|   |
| 9. STRUCTURAL a. wood frame with interlocking joints  |
| SYSTEM: b. wood frame with light members X  |
| (if known) c. masonry load bearing walls $\square$  |
| d. metal (explain)  e. other  |
| e. other  |
| 10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐   |
| 11. INTEGRITY: a. original site 🗵 b. moved 🗀 if so, when?   |
| c. list major alterations and dates (if known):   |
| #50: new first floor window and door: new siding.   |

#50: new first floor window and door; new siding. #48: new shingles.



13. MAP:



Roll #Q7; Negative #10 HOUSE #52; South & East (front) Sides.

| . 14. | THREATS TO BUILDING: a. none known  b. zoning  c. roads  c. roads                   |
|-------|---|
|       | d. developers  e. deterioration  f. other:  |
| 1,5   | RELATED OUTBUILDINGS AND PROPERTY:  |
| .15.  | a harn b carriage house c. garage   |
|       | a. barn b. carriage house c. garage d. privy e. shed f. greenhouse                  |
|       | g. shop  h. gardens   |
|       | i. landscape features:  |
|       | i other   |
| 16.   | SURROUNDINGS OF THE BUILDING (check more than one if necessary):                    |
| 10.   | a. open land □ b. woodland □  |
|       | c. scattered buildings  |
|       | d. densely built-up   e. commercial   |
|       | f. industrial  g. residential  🔀  |
|       | f. industrial g. residential 🗵  |
|       |   |
| 17.   | INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:                                     |
|       | (Indicate if building or structure is in an historic district)                      |
| mh1   | s is a group of five Victorian houses on the west side of Park Avenue,              |
| hetu  | ween Main Street and Union Boulevard. It is surrounded by an area                   |
| Of n  | nixed usage, including commercial and residential structures - some                 |
| of v  | which are architecturally significant.  |
|       | OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): |
|       |   |
| This  | group of five houses is a fine example of Victorian structures in                   |
| tne   | area. They retain much of their original detail, including                          |
| pocr  | nes with turned posts, vergreboards, towers, friezes, brackets,                     |
| stal  | ined glass windows, shingles, and clapboard.  |
|       |   |
| SIG   | NIFICANCE ,   |
| 19.   | DATE OF INITIAL CONSTRUCTION: unknown   |
|       |   |
|       | ARCHITECT: unknown  |
|       | າກໄກດາຫ   |
|       | BUILDER: unknown  |
|       | THE TOTAL AND ADDITIONAL INDODE ANCE.   |
|       | HISTORICAL AND ARCHITECTURAL IMPORTANCE:  |
| #42   | has a square tower with apointed roof and finial, brackets, and frieze              |
|       | Original windows include stained glass panes around the upper sash.                 |
|       | Original porch with turned posts, decorative balustrade, and ginger-                |
|       | bread. Queen Anne style.  |
| #46   | has a suare tower with a pointed roof, original clapboard and shingles              |
|       | The gable and tower have multi-paned windows. Original porch.                       |
|       | Picket fence. Queen Anne style.   |
| #48   | has an original porch with turned posts, curved stickwork in the                    |
|       | gable, exposed rafter ends, and brackets.   |
| #50   | has an original porch with turned posts and a balustrade. Original                  |
|       | windows, cross gables. (Continued on attached sheet)                                |
|       | SOURCES:  |
| Atla  | es of the Ocean Shore of Suffolk County, L.I. (Westerly Section).                   |
| Broo  | oklyn & Manhattan: E. Belcher Hyde, 1915. Volume I. Plate 21.                       |
|       |   |
| 22.   | THEME:  |
| Rega  | earch by the Society for the Preservation of Long Island Antiquities.               |
|       | lith Saltzman)  |
|       | ALL VIII OF COME OF CONTRACTOR OF   |