BUILDING-STRUCTURE INVENTORY FORM	FOR OFFICE USE ONLY  BA 11
DUILDING-STRUCTURE INVENTORT FORM	UNIQUE SITE NO. 163-05-0411-029
DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION	QUAD
ALBANY, NEW YORK (518) 474-0479	SERIES green
YOUR NAME: Town of Islip Town Hall	DATE: Sept. 10, 1979
YOUR ADDRESS: 655 Main St., Islip	보고 물로 가는 사람들이 되었다. 그는 사람들이 되었다면 하는 것이 되었다면 되었다면 되었다면 되었다.
[20] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	불통 중앙 살았다. 하다는 경우 회사에 되는 것이 되었다는 그 보다는 한 사람들이 되었다.
ORGANIZATION (if any): Dept. of Planni	ng and Development
* * * * * * * * * * * * * * * * * * * *	
IDENTIFICATION	
1. BUILDING NAME(S): Watson house (fo 2. COUNTY: Suffolk TOWN/CITY: Is	1ip VILLAGE: Bayport
3. STREET LOCATION: 386 Middle Rd., sout	Ander cast of Eay Ave.
4. OWNERSHIP: a. public □ b. private <b>E</b> 5. PRESENT OWNER: Watson, William	ADDRESS: 3729 Windward Way, Columbus, ohio residuce
6. USE: Original: <b>residence</b> F	Present: residuce
7. ACCESSIBILITY TO PUBLIC: Exterior visible fro Interior accessible	om public road: Yes \( \omega \) No \( \omega \) : Explain \( \omega \) appointment
<u>DESCRIPTION</u>	c. brick □ d. board and batten □
	g. stucco O other:
9. STRUCTURAL a: wood frame with interlocking	oints []
SYSTEM: b. wood frame with light memb	X 2nac
(if known) c. masonry load bearing walls  d. metal (explain)	
e. other	2. 하마마지막 일부리 연락을 하는 사람이 되었습니다. 하지 않는 하는 사람들이 가지 않을 경우로 가를 받았다.
10. CONDITION: a excellent □ b. good ▼ c. 11. INTEGRITY: a original site ▼ b. moved □	fair \( \square \text{d. deteriorated } \square \)  if so,when?
c. list major alterations and dates (if	known):
Porch altered and porte-cochere ad	ded c. 1900.
12. PHOTO: BLW I, # 9A from NW, fromt	3. MAPBowe, Albertson Sewer Maps, Bayport Q16
도를 모습니다. 전에 있었다. 이 생각들이 있다면 이번 그들도 보고 보고 이 이번 것을 보였다. 이 기계 작은 경기는 전기를 통하기 있습니다. 이 전기를 모음하는 경기를 모습니다.	
	The state of the s
	Dation Dation
	MIDDLE ROND
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	1 Do 19 5 7 7 7 1

14.	THREATS TO BUILDING: a. none known k b. zoning c. roads c. roads d. developers e. deterioration f. other: house empty and for sale.
15.	f. other:
	d. privy  e. shed  f. greenhouse  i. landscape features:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up  e. commercial  f. sindustrial  g. residential  t.  h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
	This house is located in Middle Road, Bayport, where many of the homes date back over one hundred years.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
<u>SIG</u> 19.	<u>NIFICANCE</u> DATE OF INITIAL CONSTRUCTION: <u>after 1873, before 1915.</u>
	ARCHITECT:
	BUILDER
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:  Two and one-half story, three bay, gable roof with gable end to street, and with two bay, two story wing on east. Porte-cochere on west. Window-head with drops on wing. Remains of Italianate decoration on first floor window heads. Front door with transom with leaded glass. Built after 1873, with porch and porte-cochere in the style of 1900.  This house belonged to E.E. Brown in 1915.
21.	SOURCES: Belcher-Hyde, E., Atlas of Suffolk County, Brooklyn: 1915, Bayport, p. 32.

Residential.

22. THEME: