## FORM 15C

## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY	.0
11/2-04-71/19-	(D)->
UNIQUE SITE NO. 103-05-0138-	G-T-#57
QUAD	- 0.1. "JI
SERIES	
NEG. NO.	

ISLIP

YOUR NAME: Town of Islip Town Hall	DATE: September 24, 2975
<del>_</del> · · · · <del></del>	TELEPHONE: (516) 581-2000

ORGANIZATION (if any): Department of Planning, Housing & Development

••••••••••••••••••••••••••••••••••••••
* * * * * * * * * * * * * * * * * * *
IDENTIFICATION
I. BUILDING NAME(S): Central Islip State Hospital's Photo Lab; Originally the
2. COUNTY: SUITOIK TOWN/CITY: ISIIP VILLAGE Central Isl. Laboratory
2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE Central Isl. Laboratory 3. STREET LOCATION: East of Carleton Ave. (east of Group M Buildings)
4. OWNERSHIP: a. public L b. private
5. PRESENT OWNER: ADDRESS:
6. USE: Original: Laboratory Present: Abandoned Photo Lab
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No R Permission re-
Interior accessible: Explain By appointment only quired.
DESCRIPTION QUITED:
8. BUILDING a. clapboard _ b. stone _ c. brick X d. board and batten _
MATERIAL: e. cobblestone  f. shingles g. stucco other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members
(if known) c. masonry load bearing walls <b>KX</b>
d. metal (explain)
e. other
10. CONDITION: a. excellent D b. good C c. fair X d. deteriorated D
11. INTEGRITY: a. original site 🖾 b. moved 🗌 if so, when?
c. list major alterations and dates (if known):



Roll #Q7; Neg. #1 South side

HP-1

14. THREATS TO BUILDING: a. none known  b. zoning  c. roads  c. deterioration  e. deterioration	
f. other:  15. RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house  c. garage  d. privy  e. shed  f. greenhouse    g. shop  h. gardens  i. landscape features:	
j. other:	
d. densely built-up  e. commercial  f. industrial  g. residential  h. other:	
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)	
Central Islip State Hospital is located on a 1000 acre wood running from Clayton St. to Southern State Parkway, on both Carleton Ave. The grounds contain buildings from various poin in various architectural styles, including Tudor and Colonia	sides of
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known	n):
This one story brick building has a sate roof and decorative rafter ends. It has a hipped roof with projecting gabled verthe nine-over-nine windows have lugsills. There is a four pabove the front door. The basement is partially above ground an exterior entrance.  SIGNIFICANCE  19. DATE OF INITIAL CONSTRUCTION: circa 1908	ents. Dane transom Id, and has
ARCHITECT:	
BUILDER: Commercial Const. Co.	_
This building was originally the Laboratory for the Central State Hospital. In 1913 an important discovery, referred to "The Breakthrough" took place here. Dr. J.W. Moore and Dr. established the connection of general paresis with syphilis discovering the spirocheta pallida in 12 out of 70 brain stu After use as the Laboratory, the building became a photo lab is abandoned at present. But the one story brick building hits original slate roof, exposed rafter ends, and architrave	as Neguchi by dies.
21. SOURCES:	
Bellsmith, Ethel. <u>History of Central Islip State Hospital:</u> (Unpublished material by the Supervisor of Social Work)	1887-1946.

Research by the Society for the Preservation of Long Island Antiquities. (judith saltzman)