BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	_CO3>
100 00 - TUTD.	
UNIQUE SITE NO. 102-05-01.37	
	10.1. # 70
QUAD	
SERIES	
NEG. NO	

YOUR NAME:	Town of Islip	DATE: September 24, 1975
	Town Hall	
VOLID ADDDESS.	655 Main Street	TELEPHONE (516) 581-2000

ORGANIZATION (if any): Department of Planning, Housing & Develop	ment
	5.137-
IDENTIFICATION	- 147
1. BUILDING NAME(S): Central Islip State Hospital's MacGregor & Sm	ith Groups
2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Central Is	lip (M & S
2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Central Is 3. STREET LOCATION: East of Carleton Avenue, on access roads	
4. OWNERSHIP: a. public \(\overline{\mathbb{L}}\) b. private \(\overline{\mathbb{D}}\)	
4. OWNERSHIP: a. public b. private 5. PRESENT OWNER: ADDRESS: ADDRESS:	
6. USE: Original: Housing for patients Present: Abandoned	
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No 🗴	
Interior accessible: Explain Hazardous	
Interior accessible: Explain Hazardous Permission required to enter area.	
8. BUILDING a. clapboard b. stone c. brick d. board and batten	
MATERIAL: e. cobblestone f. shingles g. stucco other:	
MILDIMID.	
9. STRUCTURAL a. wood frame with interlocking joints	
SYSTEM: b. wood frame with light members	
(if known) c. masonry load bearing walls 🖾	
d. metal (explain)	
e. other	
0. CONDITION: a. excellent b. good c. fair d. deteriorated	
1. INTEGRITY: a. original site \(\mathbb{Z} \) b. moved \(\mathbb{D} \) if so, when?	
c. list major alterations and dates (if known):	
One building in Smith Group burned; one knocked down.	

12. PHOTO:

13. MAP:

See attached map.



Roll #Q7; Neg. #2
HP4 Building in M Group

14.	THREATS TO BUILDING: a. none known b. zoning c. roads c. deterioration c. coads c. deterioration c.
	f. other: RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage d d. privy e. shed f. greenhouse g. shop h. gardens i. landscape features:
16.	j. other: SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
arcl	tral Islip State Hospital is located on a 1000 acre wooded property grounds contain buildings from various periods and in various nitectural styles. These two clusters of buildings are in the or Revival style, as are several other hospital structures.
Theswith contact kito	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): se Tudor Revival Buildings are primarily two and one-half stories, a brick first stories, and stucco second stories. Each group tains a one and one-half story building which was used as chen and dining room. IFICANCE
	ARCHITECT: Franklin B. Ware. State anch.
	BUILDER:
Thes Elir cons one buil and on t Revi dorm diam gabl 21. S	HISTORICAL AND ARCHITECTURAL IMPORTANCE: se structures were originally built for the patients of Central of State Hospital. The Smith Group, built in 1911, originally sited of seven buildings, one of which is now knocked down, and of which is burnt. The MacGregor Group, built in 1913, has four dings. The one and one-half story structures were used as kitchen dining rooms. The two and one-half story buildings had day-rooms the first floors and sleeping quarters on the second. These Tudor eval buildings have porches with Tudor arches, brackets at the ers, window heads, and eaves. The Tudor style windows have enond-paned transoms. The buildings have slate gabled roofs and ed dormers. The wide brick chimneys are supported with iron braces our leaf anchors. smith, Ethel. History of Central Islip State Hospital: 1887-1946. Sublished material by Supervisor of Social Work)
22.	гнеме:

Research by the Society for the Preservation of Long Island Antiquities. (Judith Saltzman)

