

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 10305 060897
QUAD _____
SERIES _____
NEG. NO. _____

Form 14

YOUR NAME: B. Van Liew, Consultant/WHC DATE: 5/8/83

YOUR ADDRESS: Box 416, St. James, I. I. TELEPHONE: 516-584-5600
11780

ORGANIZATION (if any): _____

IDENTIFICATION

T.B. Crescent

- 1. BUILDING NAME(S): Buildings 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, & 87
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Central Islip
- 3. STREET LOCATION: _____
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: New York State ADDRESS: _____
- 6. USE: Original: T.B. patients Present: vacant
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain _____

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints
(if known) b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO: CI-WHC-r-2, 8 from NW

13. MAP: NYS DOT-Bayshore Quad



HP-1 fronts of buildings
B-1, B-2, B-3, B-4



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: _____
 j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
 (Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1940

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The building is a fascinating semi-circle of 12 identical, 1-story cross-shaped, gable roof, red-brick buildings, 6 of which are on the west of the A-B Center (Bldg. 75) kitchen building and the other 6 are located east of the A-B Center (Bldg. 75). The west buildings, which are identified as A-1, A-2, A-3, A-4, A-5 & A-6, have open porches along each east facade either side of the projecting, 3 bay wing which has a metal pagoda hood. The east buildings, #'s B-1, B-2, B-3, B-4, B-5 & B-6 have open porches along each west facade on either side of their projecting 3-bay wing which also has a metal pagoda hood. Also each building has an entrance with a metal pagoda hood. These 13 structures radiate out from a semi-circular drive, are connected by a 1-story brick

21. SOURCES: and

Atlas of the Ocean Shore of Suffolk Co. (westerly section)
 N.Y., E. Belcher Hyde, 1915, Plate 6

20 continued: corridors of 6 bays each. Each bay has an octagon window except the bays between, B-3, & B-4, A-3 & A-4.



porch side of Building B-6
Photo:CI-WHC-r-2,7 from SW




one of the corridors
Photo:CI-WHC-r-2,11 from NW



Between Buildings A-4 & A-3

Photo:CI-WHC-r-2,4 from South




Building A-4, Photo:CI-WHC-r-2,2 from SW



Building A-3

PORCH

Photo:CI-WHC-r-2,3 from SE



Building A-4
from back

Photo:CI-WHC-r-2,5 from SW