

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

H 14

UNIQUE SITE NO. 103-05-0594-HSP
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: B. Van Liew, Consultant/ NSF DATE: 8/79
N Sherrill Foster

YOUR ADDRESS: Box 416, St. James, L.I. TELEPHONE: 516-584-5600

ORGANIZATION (if any): Natural Heritage Trust

IDENTIFICATION TAYLOR ESTATE: CARRIAGE BARN

- 1. BUILDING NAME(S): (Picnic Pavillion, Heckscher State Park:)
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: East Islip
- 3. STREET LOCATION: Timber Point Rd; South Side
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: LISPC ADDRESS: Belmont State Park
- 6. USE: Original: Carriage Barn Present: Picnic Pavillion
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Open to public for groups

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? 1920's
c. list major alterations and dates (if known):
Shingles above sill are regular, not scalloped as in the other buildings. possibly repaired in 1930's.

Roll 2

12. PHOTO: H 14 - 19 13. MAP: Bay Shore East Quadrangle
North East corner, North entrance facade



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: picnic area with tables
 j. other: comfort station # 13.
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: cinder parking lot

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
 (Indicate if building or structure is in an historic district)
 Pleasantly situated between open space and picnic grove.


18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
 3 bay one story hip roof wood sided building with bell cast ventilator with tu
 turned finial. Interior is open with narrow vertical siding on walls and ceiling
 similar to #15. East entrance is a T end gable roof with an octagonal ventilator
 with turned finial. Gable over door with stick style bracing, extruded rafter
 ends. Interior windows framed with grooved boards (Ca 4 " wide) with joining
 corners containing rosettes.

- SIGNIFICANCE** after 1885
19. DATE OF INITIAL CONSTRUCTION: _____
- ARCHITECT: _____
- BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
 Part of Taylor-Pyne complex. a large unaltered building of the 19th C.
 with many details still intact.

21. SOURCES: Interview with Mr. O'Neil 7/8/79

22. THEME:



Bay Shore East Quadrangle

H 14

45100

18000

423

RIVER

CONNETQUOT

PARK

STATE

HECKSCHER

East Isip

Avenue

WOODLAND

Winganshappage

Oakdale

27A

50A

27A

27A

17

17

27A

27A

Timber Pt

Nicoll Pt

West Beach

East Beach

HECKSCHER

Town Beach

