

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	<u>103-05-0586-#SP</u>
QUAD	_____
SERIES	_____
NEG. NO.	_____

H 6

YOUR NAME: B. Van Liew, Consultant/NSF DATE: 8/79
N Sherrill Foster
 YOUR ADDRESS: Box 416, St. James, L.I. TELEPHONE: 516-584-5600
 ORGANIZATION (if any): Natural Heritage Trust

***** PLUMB ESTATE; HORSE STALL AND BARN *****

IDENTIFICATION

- BUILDING NAME(S): PLUMB ESTATE; HORSE STALL AND BARN
(Asst. Superintendent's Garage, Heckscher State Park :)
- COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: East Islip
- STREET LOCATION: Timber Point Rd; South Side
- OWNERSHIP: a. public b. private
- PRESENT OWNER: LISPC ADDRESS: Belmont State Park
- USE: Original: Horse stall and barn Present: Garage and storage
- ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain _____

DESCRIPTION

- BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- CONDITION: a. excellent b. good c. fair d. deteriorated
- INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known):
Addition and enlargement, 1970

Roll 2
 12. PHOTO: H 6 - 9
 West side of Garage,
 North side of house.

13. MAP: Bay Shore East Quadrangle



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: Mowed lawn, wood fence
 j. other: Near Barn # 10
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: On park roadway of tarmac
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
 (Indicate if building or structure is in an historic district)
At right angles to residence surrounded by mowed lawn
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
1 story gable roof clapboard siding structure.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: after 1872

ARCHITECT: _____


BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Remodelling has destroyed almost all original features.
 Part of the Plumb estate.

21. SOURCES: Interview with Mr. O'Neil 7/8/79.
Interview with Betty Kuss 8/18/79. Quoting Old Oakdale History & South Side Signal 10/19/1872.

22. THEME:



East Islip

Union Sch

Oakdale

Oakdale Sch

per Wingunhauppauge

Great River

RIVER

Nicoll Bay

HECKSCHER

STATE

PARK

Bay Shore East Quadrangle

Nicoll Pt

H 6

