

BUILDING-STRUCTURE INVENTORY FORM

FOR OFFICE USE ONLY

H 12

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

UNIQUE SITE NO. 163-05-0592-HSP
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME B. Van Liew, Consultant/ NSF DATE: 8/79
N Sherrill Foster

YOUR ADDRESS: Box 416, St. James, L.I. TELEPHONE: 516-584-5600

ORGANIZATION (if any): Natural Heritage Trust

IDENTIFICATION

TAYLOR ESTATE: STABLES

1. BUILDING NAME(S): (Sign Shop Heckscher State Park.)

2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: East Islip

3. STREET LOCATION: Timber Point Rd; South Side

4. OWNERSHIP: a. public b. private

5. PRESENT OWNER: LISPC ADDRESS: Belmont State Park

6. USE: Original: Stables Present: sign shop

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other Brick foundation

9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____

10. CONDITION: a. excellent b. good c. fair d. deteriorated

11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known): _____

Roll 2

12. PHOTO: H 12 - 17
South East Corner

13. MAP: Bay Shore East Quadrangle



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: _____
 j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

Building is situated at right angles to # 11, its companion, and creates a nice unit

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

A 2½ story gable roof wood sided building with cross gable center element, surmounted by louvered ventilators with turned finial. S.E. side has paired windows with carved half timbering applied over vertical boarding over 3 bay baywindow with stick style brackets and braces. Siding is 3 layers, vertical boards, shingles and scalloped shingles.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1885

ARCHITECT: _____

BUILDER: _____


20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Part of the Taylor-Pyne estate, and a superb example of barn-utility architecture of the period. (see # 11) This architecturally important barn is a typically American 19th C. architecture. No where else in the world was so much attention given to the design of barns, and other utility structures.

21. SOURCES: Interview with Mr. O'Neil 7/8/79

Kornwolf, James D. M. H. Baillie Scott and the Arts and Crafts Movement.
 Johns Hopkins Press, Baltimore and London. Pp.38-43.

22. THEME:



" Stables. Deer Range Park.
Over 30 such buildings on place to
be headquarters for the Long Island
State Park Commission. 1925"

Coll. Heckscher State Park. # 12

SOUTH WEST CORNER

H 12