BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

UNIQUE SITE NO. 163 - 65 - 0601 QUAD SERIES NEG. NO.	FOR OFF	ICE USE C	NLY .		
SERIES	UNIQUE S	SITE NO. <u>L</u>	03-09	- 0601	_//
	THE STREET STREET	34/312 Had			4
				T.	_%\

YOUR NAME: SPLIA/Joel C. Snodgrass DATE: July 18, 1984

YOUR ADDRESS: 93 N. Country Road TELEPHONE: (516) 941-944/ Setauket, N.Y. 11733

ORGANIZATION (if any): Society for the Preservation of Long

Island Antiguities

		Service and		100					-787	
ō		_	B 70							•
ł	- 1	DE	N.		1	6. 1		45	ıĸ	
							21	- 1.3	<i>7</i> 111	1.0
	_	_								

1. BUILDING NAME(S): Kirk House

2. COUNTY: Suffolk TOWN/CITY: Islin VILLAGE Lake Ronkonkoma 3. STREET LOCATION:

Rosevale Ave.; N. SIDE; OPPOSITE OCEAN AVE 4. OWNERSHIP: a public \(\subseteq \) b private \(\overline{\mathbb{Z}} \)

5. PRESENT OWNER: Suffolk County ADDRESS:

6. USE: Original: private residence Present.

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes \square No \square

Interior accessible: Explain <u>no</u>

DESCRIPTION

8. BUILDING

e. cobblestone 🗀 f. shingles 🗷 g. stucco 🗔 other:

a. clapboard b, stone c. brick d. board and batten

9. STRUCTURAL

MATERIAL:

SYSTEM:

a. wood frame with interlocking joints [

b. wood frame with light members 🗷

c. masonry load-bearing walls (if known)

d. metal (explain)

e. other_

a. excellent

b. good

c. fair

d. deteriorated


10. CONDITION: 11: INTEGRITY:-

a. original site K b. moved . if so, when?

c. list major alterations and dates (if known): asphalt shingles

12. PHOTO: JCS84 R3#4 (from southwest) 13. MAP: NYS DOT - Patchogue Quad.





HP-1 Entrance, front. The lake is at the left.

14.	THREATS TO BUILDING:	a. none known b. zoning c. roads d. developers e. deterioration .
ing and a	7	f. other: unsympathetic restoration
15.	RELATED OUTBUILDING	s AND PROPERTY: a, barn ☑ b. carriage house □ c. garage □
		d privy \(\subseteq \ e \text{shed \(\mathbb{X} \) f. greenhouse \(\subseteq \)
		d. privy e. shed f. greenhouse g, shop h. gardens
		i landscane features:
16.	SURROUNDINGS OF THE	BUILDING (check more than one if necessary):
		a. open land 🟝 b. woodland 🔼
		c. scattered buildings 🗔
		d. densely built-up . e. commercial .
		f, industrial g. residential s
		h.other: property fronts on Lake Ronkonkoma
	A CONTRACTION OF OF	BUILDING AND SURROUNDINGS:
17.	INTERRELATIONSHIP OF	ture is in an historic district)
	The driveway of	the house enters onto a one-way, one-lane
	strip of Roseval	e Ave. that is part of a two-lane junction
		e. and Rosevale Ave.
		/ Fig. C. A (Chanyon)
18.	OTHER NOTABLE FEATU	RES OF BUILDING AND SITE (including interior features if known): 1f (2-1/2) story structure with hip roof. The
	A two and one-na	the building includes a second story oriel
	window projection	n that overhangs the front entrance, with turned
	columns arches	and balusters. Two central ornnmental chimneys
	flank a bin roof	three pane dormer on both the front and rear
	facades. Stain	glass transom windows are over the (continued)
SIG	NIFICANCE	
J19.	DATE OF INITIAL CONST	RUCTION: 1882
		unknown
	ARCHITECT:	UNKNOWIT
	BUILDER:	unknown
	BUILDER:	- Caranown
20.	HISTORICAL AND ARCHI	TECTURAL IMPORTANCE:
. <u></u> 0.	This charming st	ructure was originally owned by John Peter Kirk
	It was built to :	replace the first Kirk mansion known as "The
	Castle", which b	urned down. The present house is one of the
	few significant	turn-of-the-century mansions surviving from the
	time when Lake R	onkonkoma was a popular resort area. This is
	a water-front pr	operty on the shore of Lake Ronkonkoma.
21.	SOURCES:	
	Three Waves, by	Ann Farnum Curtis, 1976, pages 33 and 35.
	True 17-4 4 17	
22.	THEME:	
	rrepared by JoeT	C. Snodgrass, Research Assistant.

Kirk House, Lake Ronkonkoma, N.Y.

18. (cont.) first floor one-over-one-pane windows. An open hip roof wrap around porch extends from the north side, with three double french doors also with stained glass transoms and side lights. Above the porch on the north are two wall-faced doemers with stain glass transoms. A two story hip roof extension with end chimney and porch infill is located on the east side. On the west side two second story wall faced dormers with gable peaks contain triangular stained glass transoms.

Kirk House, Lake Ronkonkoma, N.Y.



JCS84 R3#7

Entrance facade at laft and service wing, from S.E. This view shows the chimneys clearly.

Kirk House, Lake Ronkonkoma, N.Y.




JCS84 R3#6

Water front facade, from N.E.



JCS84 R3#5

Water front facade and west facade, from N.W.



WILLIAM P. KIRK HOUSE Rosevale Ave., Circa 1900



