BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FUK (PERICE USE UNLY
	, i i i i i i i i i i i i i i i i i i i
UNIO	je site no. <u>10305.00085</u>
V-13175-312575	[2015 : 2015] [2015] [2015] [2015] [2015] [2015] [2015] [2015] [2015] [2015] [2015] [2015] [2015] [2015]
QUAD	
SERIE	C
NEG.	VO .
100000000000000000000000000000000000000	


ALDAMI, NEW 10	NEG. NO
YOUR NAME	:Town of Islip/SPLIA DATE: May 1990
	Town Hall, 655 Main St. /
YOUR ADDR	ESS: <u>Islip</u> , L.I., N.Y. 11751 TELEPHONE: <u>516.224.5450</u>
	ON (if any): Dept. of Planning, Housing, and Development
* * * * * * *	* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION	2½ Story House
I. BUILDING NAM	E(S): 2½ Story House Suffolk TOWN/CITY: Islip VILLAGE: Sayville
2. COUNTY:	Suffolk TOWN/CITY: Islip VILLAGE: Sayville
3. STREET LOCAT	TON: 117 Lincoln Ave.
4. OWNERSHIP:	a. public 🗌 b. private 🔼
5. PRESENT OWNE	R: ADDRESS: residence Present: residence
6. USE: Original:_	residence Present: residence
7. ACCESSIBILITY	
	Interior accessible: Explain <u>private residence</u>
DESCRIPTION	
8. BUILDING MATERIAL:	으로 보이는 것도 많아 보다. 그리고 있는 것은 사람들은 사람들은 가득을 가득하면 하는 것들다. 그리고 있는 것은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들
9. STRUCTURAL	a. wood frame with interlocking joints \Box
	b. wood frame with light members 🖾
(if known)	c. masonry load bearing walls 🗌
	d. metal (explain)
	e. other
0. CONDITION:	a. excellent \square b. good X c. fair \square d. deteriorated \square
	a. original site \(\overline{\Sigma} \) b. moved \(\overline{\Sigma} \) if so, when?
	c. list major alterations and dates (if known):

12. PHOTO:

Neg. KK XXIII-12, fm. E

13. MAP: NYS DOT composite Patchogue and Sayville Quads





14.	THREATS TO BUILDING: a, none known b. zoning c. roads c. d. developers e. deterioration □		
	f. other:		
15.	DELATED OUTBUILDINGS AND PROPERTY:		
	a. barn □ b. carriage house □ c. garage 🗷 d. privy □ e. shed □ _ f. greenhouse □		
	g. shop h. gardens large trees in yard i. landscape features: pair of large trees in yard		
	i. landscape features: Pair of large crees in yard		
in	j., other:		
10.	a, open land ∟ b. woodland ∟		
	c. scattered buildings 🗆 🗀 🗀		
	d. densely built-up □ e. commercial □ f. industrial □ g. residential 図		
	h, other:		
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:		
	(Indicate if building or structure is in an historic district)		
	117 Lincoln avenue is located on the west side of the street in a		
	residential area characterized by detached houses of varying historic age with little modern construction interspersed among the older houses.		
	역시민교로 시간 특성성 하시면 교육 전 경험 등 경험 등 경험 등 전 보고 있다면 등 전 경험 보고 있다면 하지만 하지만 하는 것이 되었다. 그는 것이 되었다는 것 같아 되었다는 것 같아 있다. 사		
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):		
	117 Lincoln Avenue is a 2½ story, L-shaped, gable roof, three bay		
	(paired window), side entrance plan house set perpendicular to the		
	street. The semi-wrap around porch features turned posts and pierced spandrels. A semi-hexagonal, single story bay window is on the south		
	facade of the ell.		
SIG	NIFICANCE		
19.	DATE OF INITIAL CONSTRUCTION: Prior to 1902		
	ARCHITECT:		
	BUILDER:		
	마른 사용 경험 경험 경험 경험 전략 경험 기계를 보고 있다. 		
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:		
	This is one of many houses that lined Lincoln Avenue between		
	Holmes Street and New Highway in 1915. All also appeared on the		
	1902 map. This is one of those that retains its integrity.		
	andre de la companya de la companya Na la companya de la		
21.	SOURCES:		
	E. Belcher Hyde. Atlas of the Ocean Shore of Suffolk County, L.I.		
	(westerly section), 1902.		
22.	THEME: 1915.		
	Research by Society for the Preservation of Long Island Antiquities -		
	The state of the s		