BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION

the state of the s	Fr. Ch. Editor State Co. Co. Co.	the second of the second of the second	114 214 11 12 18	
FOR O	FFICE US	E ONLY		
UNIQU	E SITE NO	0.10305	.coo.	134
QUĀD SERIES	A STATE OF THE STA			
NEG. N	SKREENSKALL VANK AND			


NEW YORK STATE PARKS AND RECREATION	SERIES	
ALBANY, NEW YORK (518) 474-0479	NEG. NO.	
YOUR NAME: Town of Islip/SPLIA Town Hall, 655 Main S	T. DATE: February 1990	
YOUR ADDRESS: Islip, L.I., N.Y. 11	가장 하루 5에 가고있다. 이 20일은 점점을 모습니다. 하는 사람들이 가게 되는 생각하다. 그 얼마나 아니라 하는 것이 하는 것이다. 그 것이다. 그 살이 없는데	
ORGANIZATION (if any): Dept. of Plann:	ing, Housing, and Development	
* * * * * * * * * * * * * * * * * * * *	. * * * * * * * * * * * * * * *	
<u>IDENTIFICATION</u>		
1. BUILDING NAME(S): Burke House 2. COUNTY: Suffolk TOWN/CITY: Is		
2. COUNTY: Suffolk TOWN/CITY: 19	slip	
3. STREET LOCATION: 136 Eaton Ln.		
4. OWNERSHIP: a. public 🗌 b. private 🗷		
5. PRESENT OWNER: A 6. USE: Original: residence P	ADDRESS:	
6. USE: Original: residence P	Present: residence	
7. ACCESSIBILITY TO PUBLIC Exterior visible fro	om public road: Yes 🖾 No 🗆 : Explain <u>private residence</u>	
<u>DESCRIPTION</u>		
8. BUILDING a. clapboard b. stone mATERIAL: e. cobblestone f. shingles	c. brick d. board and batten d. g. stucco do other:	
9. STRUCTURAL a. wood frame with interlocking SYSTEM: b. wood frame with light memb (if known) c. masonry load bearing walls 区 d. metal (explain)	ers □ Į	
e other possibly hol	low clay tile (wall construction	
0. CONDITION: a excellent 🗷 b. good 🗆 c.	fair d. deteriorated	
1. INTEGRITY: a, original site 🔼 b. moved 🗆		
c. list major alterations and dates (if		

12. PHOTO:

Neg. KK XII-21, fm. NE

13. MAP: NYS DOT Bay Shore West Quad





14.	THREATS TO BUILDING: a. none known 🖈 b. zoning 🗆 c. roads 🗆 d. developers 🗆 e. deterioration 🖸				
15.	f. other: RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage incorporated d. privy e. shed f. greenhouse g. shop h. gardens i. landscape features: j. other: compound wall at street line				
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings c. scattered buildings c. d. densely built-up e. commercial f. industrial s. residential h. other: creek to west				
17	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district) 136 Eaton Ln. fills the south portion of the triangle created by Eaton Ln. and Eaton Ln. Extension on a peninsula bordered by Skookwams Creek to the east, a creek to the west, and Great South Bay to the south. The house is surrounded by newer and compatibly aged residences, in- cluding a similiar though altered example directly NW.				
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): 136 Eaton Ln. is a small, 1½ story, Spanish style stucco house surrounded by a low stucco wall incorporated into the garage at the west/southwest. The wall gives the property the character of a small compound. The south facade features a colonnaded subsumed porch with thin Ionic columns. Round arch windows are featured elsewhere.				
4	NIFICANCE				
19.	DATE OF INITIAL CONSTRUCTION: c. 1915				
	ARCHITECT:				
	BUILDER:				
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE;				
	This is a most interesting and unusual small house. It is architecturally important because it represents the Spanish Revival architecture that was popular in the early 20th century.				
21,	SOURCES: E. Belcher Hyde. Atlas of the Ocean Shore of Suffolk County, N.Y. (west-				
	erly section), 1915.				
22.	THEME: Research by the Society for the Preservation of Long Island Antiquities - KEK				



Neg. KK IX-9, fm. W/SW. View of south facade colonnade from Sequams Ln./ Eaton Ln. Extension.