
BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OF	FICE USE ONLY
UNIOUE	SITE NO. 10305.000701
QUAD_	J. 12 1. 3. 12 J. 3. 3. 4. 10 J. 4
SERIES.	
NEG. NO)

YOUR NAME:	Town of Islip/SPLIA DATE: February 1990
	Town Hall, 655 Main St.
YOUR ADDRESS:	<u>Islip, L.Í., N.Y. 11751</u> TELEPHONE: 516.224.5450
	nny): Dept. of Planning, Housing, and Development
* * * * * * * * * *	
<u>DENTIFICATION</u>	
. BUILDING NAME(S):	McKenna House (?)
2. COUNTY: <u>Suffolk</u>	t TOWN/CITY: <u>Islip</u> VILLAGE: <u>Bay Shore</u>
3. STREET LOCATION:	121 Fifth Avenue
I. OWNERSHIP: a. publi	121 Fifth Avenue ic 口 b. private 図
5. PRESENT OWNER:	ADDRESS:sidencePresent:residence
o, USE: Original: <u>res</u>	<u>sidence</u> Present: <u>residence</u>
7. ACCESSIBILITY TO PU	JBLIC: Exterior visible from public road: Yes 😾 No 🗆 Interior accessible: Explain <u>private residence</u>
<u>DESCRIPTION</u>	
8. BUILDING a. MATERIAL e.	clapboard □ b. stone □ c. brick □ d. board and batten □ cobblestone □ f. shingles 😠 g. stucco □ other:
9. STRUCTURAL a.	wood frame with interlocking joints 🖳 (?)
SYSTEM; b.	wood frame with light members 🔀 (?)
(if known) c.	masonry load bearing walls 🗆
d.	metal (explain)
	other
	llent 🔁 b. good □ c. fair □ d. deteriorated □
l. INTEGRITY: a. origin	nal site 🗗 b. moved 🔲 if so,when?
	najor alterations and dates (if known):
porc	ch replaced
2. PHOTO: Neg KK V	71-12, fm. W 13. MAP : NYS DOT Bay Shore Eas





14.	THREATS TO BUILDING: a, none known 5. zoning c. roads c. developers c. deterioration c. f. other:
15.	RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage d. privy e. shed f. greenhouse g. shop h. gardens i. landscape features large trees in yard corner j. other: cottage
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings e. commercial d. densely built-up e. commercial d. f. industrial g. residential d. h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
• 6	121 Fifth Avenue is located in a mixed commercial and residential area, one of few recognizably historic buildings in the immediate area. The property retains integrity among commercial interests that surround the treed parcel.
IO.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): 121 Fifth Avenue is a two story, low hip roof Italianate house with paired brackets under the eaves. The three bay, side entrance plan principle facade contains an unusual double leaf door with a double tier of glazed panels in a segmental arch. The house features 4/4 windows.
SIG	NIFICANCE -
19.	DATE OF INITIAL CONSTRUCTION: Prior to 1858
	ARCHITECT:
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	It is believed that this house was built in the 1850's but furthur examinations of the framing is necessary to verify this. In 1858 there were at least ten houses along this road. This is the lone survivor. Its integrity is good.

22. THEME:

21. SOURCES:

Chace. Map of Suffolk County, 1858.

Research by the Society for the Preservation of Long Island Antiquities - KEK