## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

	_
FOR OFFICE USE ONLY	ž.
UNIQUE SITE NO. 103-05-0046	I SE ALCOHOL WE WE WE
QUADSERIES	No. 23
NEG. NO.	1

YOUR	NAME: _	Town	of	Islip	
		MATITA	Uol	7	

\_\_\_ DATE: \_\_\_ August 14, 1975

YOUR ADDRESS: 655 Main Street

\_TELEPHONE: (516) 581-2000


ORGANIZATION (if any): Department of Planning, Housing, & Development

。
<u>IDENTIFICATION</u>
1. BUILDING NAME(S): Fred E. Knapp House - formerly
2. COUNTY: Suffolk TOWN/CITY: ISLIP VILLAGE: Bay Shore
2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Bay Shore 3. STREET LOCATION: \$41 S. Clinton Ave. (east side, bet. Linden Pl. & Gibson)
4. OWNERSHIP: a. public  b. private  4
5. PRESENT OWNER: ADDRESS:
5. PRESENT OWNER: ADDRESS: Residence Present: Residence
7 ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Ves W. No
Interior accessible: Explain By appointment only.
DESCRIPTION THE HEADY CONTROL OF THE PROPERTY
8. BUILDING a. clapboard \( \subseteq \text{b. stone} \( \subseteq \text{c. brick} \( \supseteq \text{d. board and batten} \)
MATERIAL: e. cobblestone  f. shingles  g. stucco  other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members 🖾
(if known) c. masonry load bearing walls
d. metal (explain)
• e. other
10. CONDITION: a. excellent   b. good   c. fair   d. deteriorated
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
c. list major alterations and dates (if known):

12. PHOTO:

HP-1

Bay Shore Roll #Q4; Neg. #4
West (front) & South Sides.



14.	THREATS TO BUILDING: a. none known   b. zoning   c. roads
	d. developers  e. deterioration  f. other:
15.	RELATED OUTBUILDINGS AND PROPERTY:
13.	a. barn b. carriage house c. garage
	d. privy $\square$ e. shed $\square$ f. greenhouse $\square$
	g. shop h. gardens l
	i. landscape features:
	j. other: (healt more than one if necessary):
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland
	c. scattered buildings
	d. densely built-up □ e. commercial □
	f. industrial 🔲 g. residential 🔯
5	h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
Thi	s house is in a residential area which runs south from Main Street
	the Great South Bay. There are numerous houses of architectural
	nificance in the area, particularly those from the Victorian
Era	
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Thi	s house has its original shingles, windows, and porch. The porch
	classical columns with a simple balustrade. There is a slight
pro	jection with coupled columns at the porch's entrance stairs.
The	re is a projecting polygonal front bay as well.
CICI	
	NIFICANCE  DATE OF INITIAL CONSTRUCTION: Unknown
19.	DATE OF INTIAL CONSTRUCTION. CHENTOWIT
	ARCHITECT: unknown
	BUILDER: unknown
	BOILDER: CIRCLE WIT
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	s shingled house has interesting massing and original detail.
At	the south end of the front facade is apparticularly fine
ori	el window with long brackets. There is also an eyebrow
win	dow in the roof of the south facade. On the first and second
flo	ors there are original windows with pointed panes in the
	er sash. The house's projections include the porch entrance
	polygonal front bay. foundation is brick, as is the corbelled chimney.
THE	Houndacton is prick, as is one corpetted offinitely.
21	SOURCES:
	as of the Ocean Shore of Suffolk County, L.I. (Westerly Section).
₩o1	ume I. Amityville to Eastport Inclusive. Brooklyn & Manhattan:
	Belcher Hyde, 1915. Plate 21.
22.	THEME: (1) The state of the sta
	earch by the Society for the Preservation of Long Island Antiquities.
UU	dith Saltzman)