

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 103-05-0066
QUAD _____
SERIES _____
NEG. NO. _____

III-4
D01

YOUR NAME: Town of Islip DATE: August 7, 1975
Town Hall

YOUR ADDRESS: 655 Main St. TELEPHONE: (516) 581-2000

ORGANIZATION (if any): Department of Planning, Housing, & Development

IDENTIFICATION

- 1. BUILDING NAME(S): (Ski Shop)
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Bay Shore
- 3. STREET LOCATION: 112 - 106 Main St. (South side, bet. Ocean and Park)
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: _____ ADDRESS: _____
- 6. USE: Original: _____ Present: _____
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain during store hours

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints
(if known) b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known):
Extension of stores on first floor front facade.

12. PHOTO:

13. MAP:



HP-1 Bay Shore Roll #Q3; Neg. #4

14. THREATS TO BUILDING: a. none known b. zoning c. roads
d. developers e. deterioration
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn b. carriage house c. garage
d. privy e. shed f. greenhouse
g. shop h. gardens
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land b. woodland
c. scattered buildings
d. densely built-up e. commercial
f. industrial g. residential
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

The building is on a main street, surrounded by similar commercial buildings, though from varying periods. Some of the near-by structures are of architectural significance, though most have undergone extensive remodelling.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

This cluster of three stores is housed in a Victorian structure with a variety of architectural features. The front gable has variegated shingles with a semi-circular window with molded architrave. Number 112, apparently built at a different time than the main structure, has a Palladian window with the roof line following SIGNIFICANCE the line of the window.

19. DATE OF INITIAL CONSTRUCTION: unknown

ARCHITECT: unknown

BUILDER: unknown

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Architecturally, the building yields a variety of Victorian elements and ornaments. There is a mixture of decorative shingle and clapboard; projecting eaves with decorative brackets, a gabled dormer with triangular brackets, a vergeboard on the south facade. Despite remodelling, particularly at the first floor level, the building maintains its Victorian qualities of massing and texture, as well as much of its original ornament.

Mrs. G. Stellenwerf in 1915.

21. SOURCES: ANDERSON PHOTO-L.D. ROGERS PRINT
1915 E. Belcher Hyde

Note: See #25 Ocean Avenue Form (III-12)

22. THEME:

Old photo by Anderson

III-4

Main Street looking east from Ocean Avenue

