BUILDING-STRUCTURE INVENTORY FORM	T-7
UNIQUE SITE NO. $\frac{10505-0010}{5} + 52$	31
VIEW YOR MISTORIC PRESERVATION QUAD	
NEW YORK STATE PARKS AND RECREATION SERIES	
ALBANY, NEW YORK (518) 474-0479 NEG. NO	
YOUR NAME: Town of Islip DATE: August 7, 1975 Town Hall	
YOUR ADDRESS: 655 Main Street TELEPHONE: (516) 581-2000	
ORGANIZATION (if any): Department of Planning, Housing, & Development	nt
* * * * * * * * * * * * * * * * * * * *	
IDENTIFICATION	
IDENTIFICATION 1. BUILDING NAME(S): 0. Brewster House 14.945 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Bay Shore 2. COUNTY: 32 Maple Ave Viewster aide Viewster	
2. COUNTY: <u>Suffork</u> TOWN/CITY: <u>ISTIP</u> VILLAGE: <u>Bay Shore</u> 3. STREET LOCATION: <u>32</u> Maple Ave, <u>(west side, bet. Gibson St. & Map</u>	
4. OWNERSHIP: a. public \Box b. private $\overline{\mathbb{X}}$	
5. PRESENT OWNER: ADDRESS: 6. USE: Original: Residence Present: Residence	
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes I No I Interior accessible: Explain By appointment only	
DESCRIPTION	
8. BUILDING a. clapboard \Box b. stone \Box c. brick \Box d. board and batten \Box	
MATERIAL: e. cobblestone f. shingles XX g. stucco other:	
9. STRUCTURAL a. wood frame with interlocking joints	
SYSTEM: b. wood frame with light members XX	
(if known) c. masonry load bearing walls	
d. metal (explain)	
e. other 10. CONDITION: a. excellent \Box b. good X c. fair \Box d. deteriorated \Box	
10. CONDITION: a. excellent \Box b. good \square c. fair \Box d. deteriorated \Box 11. INTEGRITY: a. original site \square b. moved \Box if so,when?	
c. list major alterations and dates (if known):	
New shingles.	
A A A A A A A A A A A A A A A A A A A	
[N, v]	
12. PHOTO:	
TEIRSON TOGT	4,
	577
	Ľ
	1
	-
	7
	m
#32 2	Are
	- ver

Bay Shore Roll #Q3; Neg. #7

HP-1

14.	THREATS TO BUILDING:		
		d. developers 🔲 e. deterioration 🗌	
		f. other:	
15.	RELATED OUTBUILDING	S AND PROPERTY:	
		a. barn 🖾 b. carriage house 🗌 c. garage 🗌	
	n an	d. privy 🗌 e. shed 🗌 f. greenhouse 🗌	
		g. shop 🗋 h. gardens 🗋	
		i. landscape features:	
		j. other:	
16.	SURROUNDINGS OF THE	BUILDING (check more than one if necessary):	
		a. open land \Box b. woodland \Box	
		c. scattered buildings	
		d. densely built-up 🗌 e. commercial 🗌	
		f. industrial 🗌 g. residential 🖾	
		h other:	

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)

This house is in a residential area between Main Street and the Great South Bay. There are many houses of architectural significance here, primarily from the Victorian Era, and generally in the Queen Anne or Italianate styles.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): This Queen Anne house has a typical polygonal tower capped with a pointed roof. There are eight over eight windows in the upper story of the tower. The porch extends along the front and side of the house and has posts with simple arches. There is a porte-cochere as well. The main gable has a Palladian window.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: unknown

ARCHITECT: unknown

BUILDER: unknown

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

This house with its polygonal tower, extensive porch, and projections is a good example of the Queen Anne style. There is leaded glass in the front door and its flanking windows. On the north side, there is a projecting bay with a flat roof and cornice. The foundation is brick, as is the corbelled chimney. Thw windows are original (two over two windows onthe first and

The windows are original (two over two windows on the first and second floors) and have a simple molded trim. The porch entrance is pedimented; the portion of the second floor above it is slightly recessed.

21. SOURCES:

Atlas of the Ocean Shore of Suffolk County, L.I. (Westerly Section). Volume I. Amityville to Eastport Inclusive. Brooklyn & Manhattan: E. Belcher Hyde, 1915. 22. THEME:

Research by the Society for the Preservation of Long Island Antiquities.

200