
BUILDING-STRUCTURE INVENTORY FORM

FOR OFFICE U	SE ONLY						
UNIQUE SITE N	o. 103	5-05	F-010	23	-00J	IIIExt	
QUAD					No. 1	4	
SERIES				_			
NEG. NO			1 1	_ 1			

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479	QUADNO.
YOUR NAME: Town of Islip	DATE: September 10, 1975
Town Hall YOUR ADDRESS: 655 Main Street	
ORGANIZATION (if any): Department of	Planning, Housing & Development
* * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * * * * * * *
1. BUILDING NAME(S): House at #58 Ocean	Avenue
1. BUILDING NAME(S): House at #58 Ocean 2. COUNTY: Suffolk TOWN/CITY:	Islip VILLAGE: Bay Shore
3. STREET LOCATION: 200 OCEAN AVE. (WE	st_side, south of Linden Place)
4. OWNERSHIP: a. public □ b. private ☒☒	불어가 맞게 함께도 있다고 되었다면 살은 그 없다
5. PRESENT OWNER: 6. USE: Original: Residence	ADDRESS:
6. USE: Original: Residence	Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible for	rom public road: Yes 🖾 No 🗀
	e: Explain By appointment only
DESCRIPTION	
8. BUILDING a. clapboard □ b. stone □	c. brick d. board and batten
MATERIAL: e. cobblestone \square f. shingles	g. stucco other:
O OTENION ID AT	
9. STRUCTURALSYSTEM:a. wood frame with interlockingb. wood frame with light mem	
그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	
(if known) c. masonry load bearing walls [d. metal (explain)	불과학 화면에 살았다면 얼마 고독에 나타갔다면요 않다.
e. other	
10. CONDITION: a excellent \(\subseteq \) b. good \(\subseteq \)	fair d deteriorated
	if so,when?
c. list major alterations and dates (if	
House has been remodelled.	
Porch severely altered.	MATICOM .
TOT OIL BOACLOTA STREET GO.	





Bay Shore Roll #Q6, Neg. #2 Front facade.

14. THREATS TO BUILDING: a. none known b. zoning c. roads d. developers e. deterioration f. other:
15. RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage d. d. privy e. shed f. greenhouse g. shop h. gardens d. landscape features: j. other:
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land □ b. woodland □ c. scattered buildings □ d. densely built-up □ e. commercial □ f. industrial □ g. residential ☑ h. other:
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district) This house is in a residential area which runs south from Main Street to the Great South Bay. There are numerous houses of architectural significance in the area, ranging from Victorian and Colonial Revival Houses to simple baymen's cottages.
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): This shingle house has a projecting center bay, with a curving sweep of roof above diamond-paned casement windows. There are original brackets at the roof's overhang. There is a small shed roofed dormer. The two-over-two windows have simply molded architraves.
SIGNIFICANCE 19. DATE OF INITIAL CONSTRUCTION: unknown
ARCHITECT: unknown
BUILDER: unknown
Despite remodelling, this house retains much of its original detail, i.e., brackets and diamond-paned casement windows. The house is gable roofed. The front gable has a small rectangular casement window. Below this is the curving sweep of roof and a large diamond-paned casement window. The chimneys are corbelled. This may have been the C.E. Grandeman House in 1915.
21. SOURCES: Atlas of the Ocean Shore of Suffolk County, L.I. (Westerly Section). Brooklyn & Manhattan: E. Belcher Hyde, 1915. Volume I. Plate 21.
22. THEME:
Research by the Society for the Preservation of Long Island Antiquities (Judith Saltzman)