BUILDING-STRUCTURE INVENTORY FORM


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR O	FFICE USE ONLY
UNIOL	E SITE NO. 10.305.000705
QUAD	DUITE NO. ING. ING. ING.
SERIES	A SERVICE OF THE PARTY OF THE P
NEG. N	<u>(O,</u>

ALBANT, NEW TOP	CK (518) 4/4-0479)	NEG. NO.	
YOUR NAME		of Islip/SPLIA		. February 1990
		Mall, 655 Main	St.	
YOUR ADDRI	ESS:Islip,	L.I., N.Y. 11	751 TELEPHONE	516.224.5450
ORGANIZATIO	ON (if any):	Dept. of Plan	ning, Housing	, and Development
* * * * * * * *		* * * * * * *	* * * * * *	* * * * * * * * * *
IDENTIFICATION				
1. BUILDING NAME 2. COUNTY:	(S): Suffall:	rils. Brown Ho	use	
2. COUNTY: 3. STREET LOCATI	OULTOIK 71 E	_TOWN/CITY:	^{11p} VI	LLAGE: West Bay Shore
3. STREET LOCATI	ON::NO	South Country	road	
4. OWNERSHIP:	a. public 🗀	b. private 🗗		
5 PRESENT OWNER	p.	Δ	DDRESS:	
6. USE: Original:	residence	Pr	esent: res	idence
7. ACCESSIBILITY	TO PUBLIC:	Exterior visible from	n public road: Ye	s 🗷 No 🗆
		Interior accessible:	Explain <u>pr</u> 1	vate residence
DESCRIPTION				
8. BUILDING	a. clapboard	□ b. stone □	c. brick 🗀	d. board and batten 🗀
MATERIAL:	e. cobblestor	ne 🗌 🛮 f. shingles 🐔	g. stucco	d. board and batten other:
9. STRUCTURAL	a. wood fran	ne with interlocking	ioints 🗍	
SYSTEM:		ne with light membe		
(if known)		oad bearing walls		
	d metal (ex	plain)		
	e. other	F****/		
0. CONDITION: a		b. good 🗆 c.	fair []	
I. INTEGRITY: 4	original cita 🟋	o. good □ C.	ıan ⊑ı d. de ∴c. ı o	terrorated [1]
I. INTEURIT.	i. Original Site (4)	b. moved 🗀	ii so,wnen!	
	. nac major afterat	tions and dates (if k	nown):	

12. PHOTO: Neg. KK VIII-10, fm. S/SE 13. MAP: NYS DOT Bay Shore West Quad





14.	THREATS TO BUILDING: a. none known ₺ b. zoning □ c. roads □ d. developers □ e. deterioration □
16	F. Other:
13,	RELATED OUTBUILDINGS AND PROPERTY:
	a. barn □ b. carriage house □ c. garage □
	d. privy □ e. shed □ f. greenhouse □ g. shop □ h. gardens □
	i landscape features:
16	SURROUNDINGS OF THE BUILDING (check more than one if necessary):
	a. open land \(\overline{\omega}\) b, woodland \(\overline{\omega}\)
	c, scattered buildings []
	d. densely built-up □ e. commercial □
	f, industrial g. residential 🛣
	h, other:
	an, vuict.
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
18,	715 South Country Road is located on the north side of the historic street opposite Gardiner County Park, a large wooded and open tract south of the highway. The house is one of several residences along South Country Road on large parcels. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	715 South Country road is a large, 2½ story, three bay, side entrance plan, gable end to the street house with a wrap-around porch. The house features a darted vergeboard and molded window lintels. The entrance door contains a transom and sidelights. A two story flat roof wing is attached to the west.
SICI	VIETCANCE
19.	
	나 일반 하는 경영을 통해 있는 경영에 가는 경험을 하는 것을 하는 것이 없는 것이 없는 것을 하는 것이 되었다. 그는 것은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들
	ARCHITECT:
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	This well preserved old house was owned by Mrs. Brown on the 1873
	atlas. It is a contributing component of the South Country Road Historic District.
21.	SOURCES:
	Beers, Comstock. Atlas of Long Island, 1873.
SANT.	
22.	THEME: Research by the Society for the Preservation of Long Island Antiquities -