## BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479 FOR OFFICE USE ONLY

UNIQUE SITE NO. 63-65-6446-6-7

QUAD\_
SERIES\_
NEG. NO. \_\_\_\_\_

BA 42

green/yellow cross-hatch

YOUR NAME: Town of Islip DATE: Sept. 10, 1979
Town Hall


YOUR ADDRESS: 655 Main St., Islip TELEPHONE: 516 524-5450

ORGANIZATION (if any): Dept. of Planning and Development

2. COUNTY:	ME(S): Flanagan house ( formerly the Clarke Smith farmhuffolk TOWN/CITY: Islip VILLAGE: Bayport
3. STREET LOCA	TION: 701 Middle Rd., north side, WE corner Fairview Ave
4. OWNERSHIP:	a. public 🔲 b. private 🗷
5. PRESENT OWN	ER: Donald Flanagan ADDRESS: 701 Middle Rd., Baypor
6. USE: Original: _	residence Present: residence
7. ACCESSIBILITY	TO PUBLIC: Exterior visible from public road: Yes No Interior accessible: Explain by appointment
DESCRIPTION	그 보다 그렇게 내용하다 보다 보는 사람들이 되었다.
8. BUILDING	a. clapboard  b. stone  c. brick  d. board and batten
MATERIAL:	e. cobblestone □ f. shingles 🗶 g. stucco □ other:
MAILMAL.	g. stace E
	사용하는 사용하는 사용하는 것이 되었다. 그런 사용하는 것이 되었다. 그런 사용하는 것이 되었다. 그런 것이 되었다. 그런 것이 되었다. 그런 것이 되었다. 그 사용하는 것이 되었다. 것이 되었다면 하는 것이 되었다면 하는 것이 되었다. 그런 것이 되었다면 하는 것이 되었다. 그런 것이 되었다. 그런 것이 되었다. 그런 것이 되었다. 그런 것이 되었다.
9. STRUCTURAL	a: wood frame with interlocking joints 🍱
9. STRUCTURAL SYSTEM:	a: wood frame with interlocking joints 🔀 b. wood frame with light members 🗌
9. STRUCTURAL	a: wood frame with interlocking joints  b. wood frame with light members  c. masonry load bearing walls
9. STRUCTURAL SYSTEM:	a: wood frame with interlocking joints  b. wood frame with light members  c. masonry load bearing walls  d. metal (explain)
9. STRUCTURAL SYSTEM: (if known)	a: wood frame with interlocking joints   b. wood frame with light members   c. masonry load bearing walls   d. metal (explain)   e. other
9. STRUCTURAL SYSTEM: (if known) 0. CONDITION:	a: wood frame with interlocking joints b. wood frame with light members c. masonry load bearing walls d. metal (explain) e. other a. excellent b. good c. fair d. deteriorated
9. STRUCTURAL SYSTEM:	a: wood frame with interlocking joints   b. wood frame with light members   c. masonry load bearing walls   d. metal (explain)   e. other

Porch and porch roof altered.

12. PHOTO: RLW II, # 16A



13. MAP: Bowe, Albertson Sewer Maps, Bayport Q16

ROAD

 $\Box$ 

	THREATS TO BUILDING: a. none known  b. zoning  c. roads  d. developers  e. deterioration  f. other:
15.	RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house c. garage  c. garage  d. privy c. shed f. greenhouse c. garage  c. ga
16	j. other:  SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up e. commercial  f. industrial :g. residential  h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
	This house is located on Middle Road, Bayport, where many of the houses are over one hundred years old.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	사 사용과 이 사용한 다음과 공료들은 사용하는 통법이 들면 사용하는 사용하는 사용하는 사용하는 것이 되었다. 그 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는
<u>SIG</u> 19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: before 1858*, c. 1810**
<b>SIC</b> 19.	DATE OF INITIAL CONSTRUCTION: before 1858*, c. 1810**  ARCHITECT:
SIG 19.	DATE OF INITIAL CONSTRUCTION: before 1858*, c. 1810**
19.	DATE OF INITIAL CONSTRUCTION: before 1858*, c. 1810*  ARCHITECT:  BUILDER:
19.	DATE OF INITIAL CONSTRUCTION:before 1858*, c. 1810**  ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: Twostory, three bay, gable roof house with gable end to the street, and one and one-half story wing on east with sweeping roof over porch. This was the Clarke Smith farmhouse, built c. 1810, according to Charles Dickerson, in A History of the Sayville Community Owner reports a brick cellar under front room.  E. Eddison owned it in 1915_AND 1902.
19 20 21	DATE OF INITIAL CONSTRUCTION:  BUILDER:  HISTORICAL AND ARCHITECTURAL IMPORTANCE:  Two story, three bay, gable roof house with gable end to the street, and one and one-half story wing on east with sweeping roof over porch. This was the Clarke Smith farmhouse, built c. 1810, according to Charles Dickerson, in A History of the Sayville Community  Owner reports a brick cellar under front room.  E. Eddison owned it in 1915, AND 1902.