BUILDING-STRUCTURE INVENTORY FORM

TUK L	iffice (JZE OV	ILY		
UNIOU	JE SITE	NO 108	30 <i>5 C</i>	100 B	10
			62.313	\$ 1 \$ 1 A 1	
QUAD	2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
SERIE	\$				
A CONTRACTOR OF THE SECOND	THE WAY SHOULD BE THE THE THE			Jane 6	
NEG. 1	ئـــــــــــــــــــــــــــــــــــــ	Allenda (M.A.A.). Terlegen a para series		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

i	υ	1	VI	511	OI.	٧J	۱(JК		11	51	l	ìК	К	. I	'K	Ŀ	۶Ŀ	ĸ	V 7	١ı	10) N		
	[,	_			~ .		8	46.0	ă		, i.		- 12	M.		7.7			I 8	M	20	156			
	V	Ł	W	Y	UI	Κŀ		51	A		Ŀ	PA	١k	ιK	S	A	NI)	КI	ΞC	R	\mathbf{E}^{p}	٧Т	1())
81					100	10-17		. 0		1000						71255	200	2.5			5 46	77	Ţ	3	
d	A	L	BA	١N	ΙY	. [NŁ	٠N		Y ()R	K	-1	5	18	1.4	17	4.	Ո4	70)				100
1				Ny		70		177			- 70		303	- 7		(E)		, E.S.		33.3	4.0			300	1

Town of Islip/SPLIA Town of Islip/SPLIA DATE: March 1990
Town Hall, 655 Main St. / YOUR NAME: ____ YOUR ADDRESS: Islip, L.I., N.Y. 11751 TELEPHONE: 516.224.5450

ORGANIZATION (if any): Dept. of Planning, Housing, and Development

IDENTIFICATION 1. BUILDING NAME(S): _____St. John Rectory 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Bohemia
3. STREET LOCATION: 1150 Locust Ave. 4. OWNERSHIP: a, public □ b. private ☑
5. PRESENT OWNER: ADDRESS: ADDRESS: residence Present: rectory 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road. Yes 🖾 No 🗆 Interior accessible: Explain private residence DESCRIPTION b. stone \square c. brick \square d. board and batten \square a. clapboard 🗆 8. BUILDING e. cobblestone [] f. shingles [] g. stucco [] other: aluminum siding MATERIAL: a. wood frame with interlocking joints 9. STRUCTURAL b. wood frame with light members X SYSTEM: c. masonry load bearing walls (if known) d. metal (explain) e. other a. excellent 🗷 b. good 🗌 c. fair 🔲 d. deteriorated 🗋 10. CONDITION: a. original site 🗵 b. moved 🗌 if so, when? 11. INTEGRITY: c. list major alterations and dates (if known):

aluminum siding added, porch enclosed.

12. PHOTO: Neq. KK XXI-14, fm. NE 13. MAP: NYS DOT Patchoque Quad





	THREATS TO BUILDING: a. none known b. zoning c. roads d. developers e. deterioration c.
15.	f. other: RELATED OUTBUILDINGS AND PROPERTY: a. barn
16.	j. other: north of convent and church (BO 18) SURROUNDINGS OF THE BUILDING '(check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
18.	The Rectory is located in a residential section of Bohemia characterized by residences of similiar scale and size. The building is next north of the large hip roof convent, also converted from a residence for church use. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	The Rectory is a 2½ story, four bay house with an L-shaped gable roof and a hip roof porch across the front.
<u>SIGI</u> 19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Prior to 1922
SIG ! [9.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Prior to 1922
<u>SIG</u> I 19.	NECANCE
SIGI 19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Prior to 1922 ARCHITECT:
19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Prior to 1922 ARCHITECT: BUILDER:
19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Prior to 1922 ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: This early 20th century house retains its general form, roof, and windows despite the porch infill. Serving as the Rectory for St. John Nepocumene Church, it - along with the Chapel (BO 18) - provide
19. 20.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Prior to 1922 ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: This early 20th century house retains its general form, roof, and windows despite the porch infill. Serving as the Rectory for St. John Nepocumene Church, it - along with the Chapel (BO 18) - provide a sense of place.
19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Prior to 1922 ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: This early 20th century house retains its general form, roof, and windows despite the porch infill. Serving as the Rectory for St. John Nepocumene Church, it - along with the Chapel (BO 18) - provide
19. 20.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Prior to 1922 ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: This early 20th century house retains its general form, roof, and windows despite the porch infill. Serving as the Rectory for St. John Nepocumene Church, it — along with the Chapel (BO 18) — provide a sense of place. SOURCES: