

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 103-05-0177 - D04
QUAD _____
SERIES _____
NEG. NO. _____

B-25

YOUR NAME: Town of Islip DATE: 8/15/75
Town Hall 655 Main St.
YOUR ADDRESS: Islip, L.I., N.Y. 11751 TELEPHONE: 516-581-2000
ORGANIZATION (if any): Dept. of Planning, Housing, & Development

IDENTIFICATION


- 1. BUILDING NAME(S): #124 Third Street
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Brentwood
- 3. STREET LOCATION: 124 Third St.
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: _____ ADDRESS: _____
- 6. USE: Original: Residence Present: Residence
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain _____

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known):
Addition to South Facade.

12. PHOTO: Negative No. C-11A

13. MAP:



14. THREATS TO BUILDING: a. none known b. zoning c. roads
d. developers e. deterioration
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn b. carriage house c. garage
d. privy e. shed f. greenhouse
g. shop h. gardens
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land b. woodland
c. scattered buildings
d. densely built-up e. commercial
f. industrial g. residential
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
#124 Third Street is set back slightly from the Southwest corner of Third Street and Third Avenue.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Original clapboard siding. Original six over six windows. Original porch with stick supports. Victorian dormers with large round headed windows. Dormers run through width of house. Pedimented gable roof. Spiralettes on gable and dormers. Many additions to all sides.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
124 Third Avenue is an early house, built in 1830 by James Crowell. The addition of a Victorian porch and dormers have given the house a Victorian appearance. Descendants of the Crowell family occupied the two and one half story house until the 1940's. An 1873 Atlas of Brentwood shows the house to be the property of Mrs. Crowell. A 1915 Atlas of Brentwood indicates that the property then belonged to Mrs. J. Bennett, a Crowell descendant. The Crowells were among Brentwood's early settlers.

21. SOURCES:
Atlas of the Ocean Shore of Suffolk County (Western Section)
New York: E. Belcher Hyde, 1915, Plate 17.

22. THEME: **Beers, F.W. Atlas of Long Island, New York. New York: Beers, Comstock, and Cline, 1873, Plate 155.**
Zwerling, Nancy. Conversation with Nancy Zwerling on 7/15/75.
Research by the Society for the Preservation of L.I. Antiquities