

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. <u>103-05-0181-004</u>
QUAD _____
SERIES _____
NEG. NO. _____

B-29
004

YOUR NAME: Town of Islip DATE: 8/15/75
Town Hall 655 Main St.
 YOUR ADDRESS: Islip, L.I., N.Y. 11751 TELEPHONE: 516-581-2000
 ORGANIZATION (if any): Dept. of Planning, Housing, & Development

IDENTIFICATION


- BUILDING NAME(S): #140 Third Street (Colson House)
- COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Brentwood
- STREET LOCATION: 140 Third St.
- OWNERSHIP: a. public b. private
- PRESENT OWNER: _____ ADDRESS: _____
- USE: Original Residence Present: Residence
- ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain _____

DESCRIPTION

- BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- STRUCTURAL SYSTEM: a. wood frame with interlocking joints
(if known) b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- CONDITION: a. excellent b. good c. fair d. deteriorated
- INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO: Negative No. C-15A

13. MAP:



14. THREATS TO BUILDING: a. none known b. zoning c. roads
d. developers e. deterioration
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn b. carriage house c. garage
d. privy e. shed f. greenhouse
g. shop h. gardens
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land b. woodland
c. scattered buildings
d. densely built-up e. commercial
f. industrial g. residential
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
#140 Third Street is on the Northwest corner of Second Avenue and Third Street. It is surrounded by trees.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Original windows. Cross gable on Roof of East facade. Gabled dormers on roof of South facade. Many additions.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
#140 Third Street reflects the change due to growth of an early Brentwood house. The structure has suffered many alterations through various additions through the years. An 1873 Atlas of Brentwood shows the property to belong to J. Colson, while a 1915 Atlas of Brentwood indicates the owner to be Mrs. Courtney.

21. SOURCES:

**Atlas of the Ocean Shore of Suffolk County (Westerly Section)
New York: E. Belcher Hyde, 1915, Plate 17.**

22. **Beers, F.W, Atlas of Long Island, New York. New York: Beers, Comstock, and Cline, 1873, Plate 155.**
Zwerling, Nancy. Conversation with Nancy Zwerling on 7/15/75.