

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY  
UNIQUE SITE NO. 103-05-0184  
QUAD \_\_\_\_\_  
SERIES \_\_\_\_\_  
NEG. NO. \_\_\_\_\_

B-32  
D04

YOUR NAME: Town of Islip DATE: 8/15/75  
Town Hall 655 Main St.  
YOUR ADDRESS: Islip, L.I., N.Y. 11751 TELEPHONE: 516-581-2000  
ORGANIZATION (if any): Dept. of Planning, Housing, & Development

\*\*\*\*\*

IDENTIFICATION


- 1. BUILDING NAME(S): #4 ~~Fourth Avenue~~
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Brentwood
- 3. STREET LOCATION: 4 ~~Fourth Ave.~~ Second St.
- 4. OWNERSHIP: a. public  b. private
- 5. PRESENT OWNER: \_\_\_\_\_ ADDRESS: \_\_\_\_\_
- 6. USE: Original: Residence Present: Residence
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes  No   
Interior accessible: Explain Privately owned

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard  b. stone  c. brick  d. board and batten   
e. cobblestone  f. shingles  g. stucco  other: \_\_\_\_\_
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints   
b. wood frame with light members   
c. masonry load bearing walls   
d. metal (explain) \_\_\_\_\_  
e. other \_\_\_\_\_
- 10. CONDITION: a. excellent  b. good  c. fair  d. deteriorated
- 11. INTEGRITY: a. original site  b. moved  if so, when? \_\_\_\_\_  
c. list major alterations and dates (if known): \_\_\_\_\_

12. PHOTO: Negative No, C-18A

13. MAP:



14. THREATS TO BUILDING: a. none known  b. zoning  c. roads   
 d. developers  e. deterioration   
 f. other: \_\_\_\_\_
15. RELATED OUTBUILDINGS AND PROPERTY:  
 a. barn  b. carriage house  c. garage   
 d. privy  e. shed  f. greenhouse   
 g. shop  h. gardens   
 i. landscape features: \_\_\_\_\_  
 j. other: \_\_\_\_\_
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  
 a. open land  b. woodland   
 c. scattered buildings   
 d. densely built-up  e. commercial   
 f. industrial  g. residential   
 h. other: \_\_\_\_\_

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
 (Indicate if building or structure is in an historic district)  
**# 4 Fourth Avenue is set back on the property among trees. There is a large wooded site bordering the East side of the property.**

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):  
**Gable roof section with half-timbering in gable. Sweeping roof down to porch with eyebrow window. Stickwork panel between to front windows of gable section on first floor. Flaring out of shingles above first floor level. Bay protruding on East facade. Original windows. Queen Anne window in gable.**

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: \_\_\_\_\_  
 ARCHITECT: \_\_\_\_\_  
 BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:  
**# 4 Fourth Avenue is a late Victorian house built between 1870 and 1880. It has many interesting details. The half-timbering effect in the gable, the wood panel between the first floor gable windows, and the eyebrow window in the entry porch roof represent a concept of Queen Anne design. The house can be found on a 1915 Atlas of Brentwood at which time it was the property of C.W. Kellum.**

21. SOURCES:  
**Atlas of the Ocean Shore of Suffolk County (Westerly Section)  
 New York: E. Belcher Hyde, 1915, Plate 17.**

22. THEME:  
**Research by the Society for the Preservation of L.I. Antiquities.**