BUILDING-STRUCTURE INVENTORY FORM	FOR OFFICE USE ONLY	18-3
	UNIQUE SITE NO. 103-05-018	5-D
DIVISION FOR HISTORIC PRESERVATION	QUAD	- -
NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479	SERIES	-
ALDA: (1, 1) (1) (1) (318) 4/4-04/9	NEG. NO	<u>- 1</u> * *
YOUR NAME: <u>Town of Islip</u> Town Hall 655 Mai	DATE: 8/15/75	
YOUR ADDRESS: Islip, L.I., N.Y. 1		<u> </u>
ORGANIZATION (if any): Dept. of Plan	ning, Housing, & Developme	nt
	en de la contra de En tra contra de la c	
* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * * *	*
IDENTIFICATION 1. BUILDING NAME (S): #7 Forus the Amon use		
2. COUNTY: Suffolk TOWN/CITY:	Islip VILLAGE: Brentwoo	d
3. STREET LOCATION: 7 FOUGh AVE.		
4. OWNERSHIP: a. public 🗋 b. private 🕱		
5. PRESENT OWNER: 6. USE: Original: Residence	ADDRESS:	<u> </u>
6. USE: Original: Residence	Present: <u>Residence</u>	
7. ACCESSIBILITY TO PUBLIC: Exterior visible Interior accessi	from public road: Yes 🛥 No 🖵 ole: Explain	
DESCRIPTION	sic. Explain	
8. BUILDING a. clapboard 🗷 b. stone [□ c. brick □ d. board and batten □)
MATERIAL: e. cobblestone 🗌 f. shingle	s 🗷 g. stucco 🗆 other:	· .
9. STRUCTURAL a. wood frame with interlock	ing joints 🕱	
SYSTEM: b. wood frame with light me		
(if known) c. masonry load bearing walls		
d. metal (explain)	<u> Anno 1988 - Anno 1989 - Anno 1989 - Anno 1989</u>	
e. other		· · · ·
10. CONDITION: a. excellent 🖾 b. good 🗆		
11. INTEGRITY: a. original site 🗷 b. moved 🗌		
c. list major alterations and dates (if known):	
12. PHOTO: Negative No. C-20A	13. MAP:	
	7 ^N 16	
	#133	
	FOUETH AV	8
		na dat na dina dina di
HP-1		

14.	THREATS TO BUILDING: a. none known I b. zoning C. roads d. developers b. zoning C. roads C. roads d. developers d. developers c. deterioration C. roads
	f. other:
15.	RELATED OUTBUILDINGS AND PROPERTY:
	a. barn b. carriage house c. garage x d. privy e. shed f. greenhouse
	a. privy \square e. shed \square i. greenhouse \square g. shop \square h. gardens \square
	i. landscape features:
	j. other:
16	SURROUNDINGS OF THE BUILDING (check more than one if necessary):
	a. open land \Box b. woodland \Box
	c. scattered buildings
	d. densely built-up 🗋 e. commercial 🗌
	f. industrial g . residential x h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
	(Indicate if building or structure is in an historic district)
	#7 Fourth Avenue is located on the Northwest corner of Fourth
	Avenue and Second Street on a site covered with trees and
	shrubery.
	Shrubery.
8.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	Built in two parts - line of demarcation between two parts
	is visible on exterior. Original porch from later period. Snow birds on the roof. Exposed rafters under eaves. Original windows.
	Snow birds on the roof. Exposed rafters under eaves. Original windows.
	Snow birds on the roof. Exposed rafters under eaves. Original windows. NIFICANCE
	Snow birds on the roof. Exposed rafters under eaves. Original windows.
	Snow birds on the roof. Exposed rafters under eaves. Original windows. <u>NIFICANCE</u> DATE OF INITIAL CONSTRUCTION:
	Snow birds on the roof. Exposed rafters under eaves. Original windows. NIFICANCE DATE OF INITIAL CONSTRUCTION: ARCHITECT:
	Snow birds on the roof. Exposed rafters under eaves. Original windows. <u>NIFICANCE</u> DATE OF INITIAL CONSTRUCTION:
<u>SIG</u> 9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. NIFICANCE DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER:
9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. NIFICANCE DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER:
9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. <u>NIFICANCE</u> DATE OF INITIAL CONSTRUCTION:
9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. <u>NIFICANCE</u> DATE OF INITIAL CONSTRUCTION:
9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. <u>NIFICANCE</u> DATE OF INITIAL CONSTRUCTION:
9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. <u>NIFICANCE</u> DATE OF INITIAL CONSTRUCTION:
9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. NIFICANCE DATE OF INITIAL CONSTRUCTION:
9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. <u>NIFICANCE</u> DATE OF INITIAL CONSTRUCTION:
9.	Snow birds on the roof. Exposed rafters under eaves. Original windows. NIFICANCE DATE OF INITIAL CONSTRUCTION:

ties EFW