

**BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY  
UNIQUE SITE NO. 103-05-0175  
QUAD \_\_\_\_\_  
SERIES \_\_\_\_\_  
NEG. NO. \_\_\_\_\_

B-22  
D04

YOUR NAME: Town of Islip DATE: 8/15/75

YOUR ADDRESS: Town Hall 655 Main St.  
Islip, L.I., N.Y. 11751 TELEPHONE: 516-581-2000

ORGANIZATION (if any): Dept. of Planning, Housing, & Development

\*\*\*\*\*

**IDENTIFICATION**

- 1. BUILDING NAME(S): \_\_\_\_\_ t
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Brentwood
- 3. STREET LOCATION: Fourth St, west side; at Third Ave; south side
- 4. OWNERSHIP: a. public  b. private
- 5. PRESENT OWNER: \_\_\_\_\_ ADDRESS: \_\_\_\_\_
- 6. USE: Original: Residence Present: Residence
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes  No   
Interior accessible: Explain \_\_\_\_\_

**DESCRIPTION**



- 8. BUILDING MATERIAL: a. clapboard  b. stone  c. brick  d. board and batten   
e. cobblestone  f. shingles  g. stucco  other: \_\_\_\_\_
- 9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints   
(if known) b. wood frame with light members   
c. masonry load bearing walls   
d. metal (explain) \_\_\_\_\_

- c. fair  d. deteriorated
- if so, when? \_\_\_\_\_
- (if known): \_\_\_\_\_



HP-1

Negative No. C-9A



14. THREATS TO BUILDING: a. none known  b. zoning  c. roads   
d. developers  e. deterioration   
f. other: \_\_\_\_\_

15. RELATED OUTBUILDINGS AND PROPERTY:  
a. barn  b. carriage house  c. garage   
d. privy  e. shed  f. greenhouse   
g. shop  h. gardens   
i. landscape features: \_\_\_\_\_  
j. other: \_\_\_\_\_

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  
a. open land  b. woodland   
c. scattered buildings   
d. densely built-up  e. commercial   
f. industrial  g. residential   
h. other: \_\_\_\_\_

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
(Indicate if building or structure is in an historic district)  
The house at the Southwest corner of Third Avenue and Fourth Street is set back from the corner among a cluster of trees.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):  
Original brick foundation. Many different types of shingles. Small Queen Anne windows. Shingled brackets flaring out of Second floor level. Flaring out of first and second floor levels. Closed eaves. Bay on the east side of house with variegated shingles and Queen Anne windows. Circular window in front gable.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: \_\_\_\_\_

ARCHITECT: \_\_\_\_\_

BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:  
The Queen Anne style house at the Southwest corner of Third Avenue and Fourth Street has many typical details common to this style. Especially noteworthy are the highly unusual large flared shingle brackets extending from the side facades supporting the East and West rooflines. The employment of at least four different kinds of shingles was typical of the Queen Anne Style, though as many as four were not used as often. The inset panels are also of interest. The house appears on a 1915 Atlas of Brentwood at which time it belonged to S.L. Palmer.

21. SOURCES:  
Atlas of the Ocean Shore of Suffolk County (Westerly Section)  
New York: E. Belcher Hyde, 1915, Plate 17.

22. THEME:  
Research by the Society for the Preservation of L.I. Antiquities  
EFW

14. THREATS TO BUILDING: a. none known  b. zoning  c. roads   
d. developers  e. deterioration   
f. other: \_\_\_\_\_
15. RELATED OUTBUILDINGS AND PROPERTY:  
a. barn  b. carriage house  c. garage   
d. privy  e. shed  f. greenhouse   
g. shop  h. gardens   
i. landscape features: \_\_\_\_\_  
j. other: \_\_\_\_\_
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  
a. open land  b. woodland   
c. scattered buildings   
d. densely built-up  e. commercial   
f. industrial  g. residential   
h. other: \_\_\_\_\_

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
(Indicate if building or structure is in an historic district)  
**The house at the Southwest corner of Third Avenue and Fourth Street is set back from the corner among a cluster of trees.**

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):  
**Original brick foundation. Many different types of shingles. Small Queen Anne windows. Shingled brackets flaring out of Second floor level. Flaring out of first and second floor levels. Closed eaves. Bay on the east side of house with variegated shingles and Queen Anne windows. Circular window in front gable.**

**SIGNIFICANCE**

19. DATE OF INITIAL CONSTRUCTION: \_\_\_\_\_  
ARCHITECT: \_\_\_\_\_  
BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:  
**The Queen Anne style house at the Southwest corner of Third Avenue and Fourth Street has many typical details common to this style. Especially noteworthy are the highly unusual large flared shingle brackets extending from the side facades supporting the East and West rooflines. The employment of at least four different kinds of shingles was typical of the Queen Anne Style, though as many as four were not used as often. The inset panels are also of interest. The house appears on a 1915 Atlas of Brentwood at which time it belonged to S.L. Palmer.**

21. SOURCES:  
Atlas of the Ocean Shore of Suffolk County (Westerly Section)  
New York: E. Belcher Hyde, 1915, Plate 17.

22. THEME:  
**Research by the Society for the Preservation of L.I. Antiquities**