
## **BUILDING-STRUCTURE INVENTORY FORM**

FOR OFFICE USE ONLY	B-15
UNIQUE SITE NO. 103-05-016)	400-
QUAD	
SERIES	
NEG. NO.	1

DIVICION FOR HIGTORIC PRECERVATION	UNIQUE SITE NO. 103 05 0101
DIVISION FOR HISTORIC PRESERVATION	QUAD
NEW YORK STATE PARKS AND RECREATION	SERIES
ALBANY, NEW YORK (518) 474-0479	NEG. NO.
YOUR NAME: Town of Islip	
Town Hall 655 Main S YOUR ADDRESS: Islip, L. I., N. Y. 1175	St. 1_TELEPHONE: 516-581-2000
ORGANIZATION (if any): Dept. of Planni	ng, Housing, & Development
* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * *
IDENTIFICATION	i del 1866 de la Caractería de la Caract
1. BUILDING NAME (S): #1749 Brontwood Ros	ad Control of the Con
2. COUNTY: SUITOIK TOWN/CITY: IS.	110 VILLAGE: Brentwood
3. STREET LOCATION: 1749 Poventwood R	tra for a company of the second
4. OWNERSHIP: a. public □ b. private ▼	
	DDRESS:
5. PRESENT OWNER: AI 6. USE: Original: Residence Pro	esent: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from	n public road: Yes 🗷 No 🗆
Interior accessible:	Explain
DESCRIPTION AND AND STORE OF THE PROPERTY OF T	en fri - Lydrefider - Lybury Ffs
8. BUILDING a. clapboard $\square$ b. stone $\square$	c. brick d. board and batten
MATERIAL: e. cobblestone  f. shingles	g. stucco other:
	强度医 <u>用</u> 的加速设施的现在分词 一直,他
9. STRUCTURAL a. wood frame with interlocking j	joints 🗷
SYSTEM: b. wood frame with light member	
(if known) c. masonry load bearing walls	Alabada da 1999, por la compania de la compania de La compania de la co
d. metal (explain)	
e. other	
10. CONDITION: a. excellent  b. good  c. t	
11. INTEGRITY: a. original site 🗵 b. moved 🗆	
c. list major alterations and dates (if ki	nown):



#1749 EIFTH AVE

DOMENT.

14.	threats to building: a. none known  b. zoning  c. roads  d. developers  e. deterioration  f. other:
15	RELATED OUTBUILDINGS AND PROPERTY:
1	a. barn b. carriage house c. garage
	d. privy e. shed f. greenhouse
	g, shon h, gardens h
	i. landscape features: j. other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):
	a. open land $\square$ b. woodland $\square$
	c. scattered buildings
	d. densely built-up 🗀 e. commercial 🗀
	f. industrial g. residential 🛣 h. other:
	h. other:
	and the state of the control of the control of the state of the control of the control of the control of the c The control of the co
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
	#1749 Brentwood Road is set back from the corner among Pine
	trees and shrubery. It is part of the wooded Brentwood Road
	streetscape.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	Original brick foundation. Original four over four and two
	over two windows. Pedimented dormer. Hip roof.
SIG	<u>SNIFICANCE</u>
19.	DATE OF INITIAL CONSTRUCTION:
	ARCHITECT:
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	The two-and-one-half story three-bay house at the Northeast
	corner of Brentwood Road and Fifth Avenue is a basically
	plain house. There is an interesting interplay of dormer and
	cross gable on the roofline. It is set among some beautiful
in the second	Brentwood Pines. It appears on a 1915 Atlas of Brentwood to have been owned by A. Martin.
21	COLIDATO
21.	SOURCES:
	Atlas of the Ocean Shore of Suffolk County (Westerly Section)
	New York: E. Belcher Hyde, 1915, Plate 17.
22.	THEME:
4.	
	Research by the Society for the Preservation of L.I. Antiquities EFW