

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. ~~10305.0166~~
QUAD 10305.000627
SERIES _____
NEG. NO. _____

B-14

9V nu #15

YOUR NAME: Town of Islip DATE: 8/15/75
Town Hall 655 Main St.
YOUR ADDRESS: Islip, .L.I., N.Y. 11751 TELEPHONE: 516-581-2000
ORGANIZATION (if any): Dept. of Planning, Housing, & Development


IDENTIFICATION


- 1. BUILDING NAME(S): #1758 Brentwood Road
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Brentwood
- 3. STREET LOCATION: 1758 Brentwood Rd.
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: _____ ADDRESS: _____
- 6. USE: Original: Residence Present: Residence
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain Privately Owned

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO: Negative No. C-0A

13. MAP: 



14. THREATS TO BUILDING: a. none known b. zoning c. roads
d. developers e. deterioration
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn b. carriage house c. garage
d. privy e. shed f. greenhouse
g. shop h. gardens
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land b. woodland
c. scattered buildings
d. densely built-up e. commercial
f. industrial g. residential
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
#1755 Brentwood Road is set back from the corner in a cluster of trees and shrubery and is part of a residential neighborhood.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Original clapboard, original windows with vertical paned upper sashes. Brackets under pediment cornice. Brackets supporting pediment. Rusticated block piers at corners of porch ballustrade with carved urns. Rusticated block foundation. Exposed rafters under roof overhang. Pedestal based SIGNIFICANCE columns supporting pedimented front porch overhang.

19. DATE OF INITIAL CONSTRUCTION: _____ (screened in) _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
#1758 Brentwood Road is an excellent example of California-Style Bungaloid houses. The pedimented overhang above the entrance is a typical detail of this style. In this case the entrance porch has been screened in. Its excellent condition and integrity of detailing make it an architecturally significant house in its area.

21. SOURCES:

22. THEME:

**Research by the Society for the Preservation of L.I.I. Antiquities/
EFW**