

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 103-05-0164
QUAD _____
SERIES _____
NEG. NO. _____

B-13
D04

YOUR NAME: Town of Islip DATE: 8/1/75
Town Hall 655 Main St.
YOUR ADDRESS: Islip, L.I., N.Y. 11751 TELEPHONE: 516-581-2000
ORGANIZATION (if any): Dept. of Planning, Housing, & Development

IDENTIFICATION


- 1. BUILDING NAME(S): #1766 Brentwood Road
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Brentwood
- 3. STREET LOCATION: 1766 Brentwood Rd.
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: _____ ADDRESS: _____
- 6. USE: Original: Residence Present: Residence
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain Privately owned

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO: Negative No. B-12A

13. MAP:



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: _____
 j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
 (Indicate if building or structure is in an historic district)
 #1766 Brentwood Road is set back from the Street on a treed lot.
 It has a barn to the west of the property. The house is surrounded by hedges,

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
 Stucco exterior finish. Large concrete columns supporting pergola of wooden beams around house. Large glass doors at pergola level. Tower on North facade. Long narrow windows flanking entrance. Barn with double gable and hip roof.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
 ARCHITECT: _____
 BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
 #1766 Brentwood Road is an unusual type of house. The pergola surrounding the east and south facade of the house give it a feeling of grandeur in a classical manner. The house and barn can be found on a 1915 Atlas of Brentwood. The property belonged to A. Noble. The stucco finish was definitely later. The original exterior finish material was probably wood siding of the same kind that covers the barn. The barn is a charming Victorian building that also shows on the 1915 Atlas.

21. SOURCES:
Atlas of the Ocean Shore of Suffolk County (Westerly Section)
 New York: E. Belcher Hyde, 1915 Plate 17.
 Beers, F.W. Atlas of Long Island. N.Y.: Beers, Comstock &
 Cline, 1873.

22. THEME: Research by the Society for the Preservation of L.I. Antiquities