

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY  
UNIQUE SITE NO. 103-05-010  
QUAD \_\_\_\_\_  
SERIES \_\_\_\_\_  
NEG. NO. \_\_\_\_\_

B-17  
D04

YOUR NAME: Town of Islip DATE: 8/15/75

YOUR ADDRESS: Town Hall 655 Main St.  
Islip, L.I., N.Y. 11751 TELEPHONE: 516-581-2000

ORGANIZATION (if any): Dept. of Planning, Housing, & Development

\*\*\*\*\*

IDENTIFICATION


- 1. BUILDING NAME(S): \_\_\_\_\_ to Sixth Ave.
- 2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Brentwood
- 3. STREET LOCATION: Brentwood Rd; east side; at Sixth Ave. & Brent-
- 4. OWNERSHIP: a. public  b. private  WOOD ROAD.
- 5. PRESENT OWNER: \_\_\_\_\_ ADDRESS: \_\_\_\_\_
- 6. USE: Original: Residence Present: Residence
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes  No   
Interior accessible: Explain \_\_\_\_\_

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard  b. stone  c. brick  d. board and batten   
e. cobblestone  f. shingles  g. stucco  other: \_\_\_\_\_
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints   
b. wood frame with light members   
c. masonry load bearing walls   
d. metal (explain) \_\_\_\_\_  
e. other \_\_\_\_\_
- 10. CONDITION: a. excellent  b. good  c. fair  d. deteriorated
- 11. INTEGRITY: a. original site  b. moved  if so, when? \_\_\_\_\_  
c. list major alterations and dates (if known):  
Later lean-to addition to East (rear) facade.  
Entrance porch not original.

12. PHOTO: Negative No. C-4A

13. MAP:



14. THREATS TO BUILDING: a. none known  b. zoning  c. roads   
 d. developers  e. deterioration   
 f. other: \_\_\_\_\_
15. RELATED OUTBUILDINGS AND PROPERTY:  
 a. barn  b. carriage house  c. garage   
 d. privy  e. shed  f. greenhouse   
 g. shop  h. gardens   
 i. landscape features: \_\_\_\_\_  
 j. other: \_\_\_\_\_
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  
 a. open land  b. woodland   
 c. scattered buildings   
 d. densely built-up  e. commercial   
 f. industrial  g. residential   
 h. other: \_\_\_\_\_

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
 (Indicate if building or structure is in an historic district)

The house on the East side of Brentwood Road opposite Sixth Avenue is set back from the Street to the North of part of the property of St. Joseph's Academy.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Original clapboard siding. Original six over six windows. Later portico over entrance. Addition to rear.

**SIGNIFICANCE**

19. DATE OF INITIAL CONSTRUCTION: \_\_\_\_\_

ARCHITECT: \_\_\_\_\_

BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The three bay one and one-half story house on the East side of Brentwood Road opposite Sixth Avenue is a simple utilitarian building. The house can be located on the 1873 Atlas of Brentwood. At that time it belonged to T.C. George, a Civil War hero. The 1915 Atlas of Brentwood shows the house to be the property of F.E. Blacker. The simple, small house has remained virtually unchanged since that time.

21. SOURCES:

Atlas of the Ocean Shore of Suffolk County. (Westerly Section)  
 New York: E. Belcher Hyde, 1915. Plate 17.

Beers, F.W. Atlas of Long Island, New York. New York: Beers,

22. THEME: Comstock & Cline, 1873, Plate 155.

Zwerling, Nancy. Conversation with Nancy Zwerling on 7/15/75.

Research by the Society for the Preservation of L.I. Antiquities