BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	B-34
UNIQUE SITE NO. 105-05-0165-	004
QUADSERIES	
NEG. NO.	


YOUR	NAME:	Town	of	Isl	lip				DATE:	8/25/75	
		Town					St	•			
YOUR	ADDRES	SISli), I	, I,	, N .	Y. 11	751	TELE	PHONE	516-581-	2000

ORGANIZATION (if any): Dept. of Planning, Housing, & Development

* * * * * * * * * * * *	* * * * * * * * * *	* * * * * * * * * * *
<u>IDENTIFICATION</u>		
1. BUILDING NAME(S):	26 重要化。 發展一起發光的時候對于複業的	Addison
2. COUNTY: Suffolk	TOWN/CITY: Islip	VILLAGE: Brentwood
3. STREET LOCATION: Madis	on Ave; west side; at s	procest southside
4. OWNERSHIP: a. public \Box	b. private 🔼	
5. PRESENT OWNER:	ADDRESS:	
6. USE: Original: Residence		
7. ACCESSIBILITY TO PUBLIC:	Exterior visible from public re	oad: Yes No 🗆
	Interior accessible: Explain	
DESCRIPTION	S වෙන එකිනම දීවලට (වෙනි. දෙම	
8. BUILDING a. clapboa	rd 🗷 b. stone 🗌 c. bric	k ☐ d. board and batten ☐
MATERIAL: e. cobbles	tone 🔲 f. shingles 🗀 g. stuc	co other:
	the complete of the property	
	rame with interlocking joints	The state of the s
	rame with light members 🗷	
	y load bearing walls	
	(explain)	
10. CONDITION: a. excellent	b. good 🗷 c. fair 🗌	d. deteriorated \square
11. INTEGRITY: a. original site \$\overline{x}\$	b. moved if so,wh	en?
c. list major alte	rations and dates (if known):	

12. PHOTO: Negative No. D-15

13. MAP: 2



14.	THREATS TO BUILDING: a. none known b. zoning c. roads e. deterioration
15.	f. other: RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage c.
	d. privy e. shed f. greenhouse g. shop h. gardens
	i. landscape features: j. other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland
	c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
	The house at the Southwest corner of Spruce Street and Madison Avenue is set back from the corner on a wooded lot.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	Variegated shingles in gable. Swag in gable under rectangular window with two side panels. Shutters (Closed). Original porch surrounding house. Flaring out at gable level with cornice line below flare. Bays extending out of sides.
SIG	
	NIFICANCE
19.	NIFICANCE DATE OF INITIAL CONSTRUCTION:
19.	
19.	DATE OF INITIAL CONSTRUCTION:
19.20.	DATE OF INITIAL CONSTRUCTION: ARCHITECT:
	DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: The house at the Soutwest corner of Spruce St. and Madison Avenue is a handsome two and one half story Queen Anne
	DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: The house at the Soutwest corner of Spruce St. and Madison Avenue is a handsome two and one half story Queen Anne design. The swag under the rectangular windows of the gable shows the date of the house to be 1892. The house can be found on a 1915 Atlas of Brentwood on which the owner
	DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: The house at the Soutwest corner of Spruce St. and Madison Avenue is a handsome two and one half story Queen Anne design. The swag under the rectangular windows of the gable shows the date of the house to be 1892. The house
	DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: The house at the Soutwest corner of Spruce St. and Madison Avenue is a handsome two and one half story Queen Anne design. The swag under the rectangular windows of the gable shows the date of the house to be 1892. The house can be found on a 1915 Atlas of Brentwood on which the owner
20.	DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: The house at the Soutwest corner of Spruce St. and Madison Avenue is a handsome two and one half story Queen Anne design. The swag under the rectangular windows of the gable shows the date of the house to be 1892. The house can be found on a 1915 Atlas of Brentwood on which the owner
20.	DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: The house at the Soutwest corner of Spruce St. and Madison Avenue is a handsome two and one half story Queen Anne design. The swag under the rectangular windows of the gable shows the date of the house to be 1892. The house can be found on a 1915 Atlas of Brentwood on which the owner was Mrs. M. White. SOURCES: Atlas of the Ocean Shore of Suffolk County (Westerly Section)
20.	DATE OF INITIAL CONSTRUCTION: ARCHITECT: BUILDER: HISTORICAL AND ARCHITECTURAL IMPORTANCE: The house at the Soutwest corner of Spruce St. and Madison Avenue is a handsome two and one half story Queen Anne design. The swag under the rectangular windows of the gable shows the date of the house to be 1892. The house can be found on a 1915 Atlas of Brentwood on which the owner was Mrs. M. White.