

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 10305.000600
QUAD _____
SERIES _____
NEG. NO. _____

HA 6

YOUR NAME: Town of Islip/SPLIA DATE: March 1990

Town Hall, 655 Main St.

YOUR ADDRESS: Islip, L.I., N.Y. 11751 TELEPHONE: 516.224.5450

ORGANIZATION (if any): Dept. of Planning, Housing, and Development

IDENTIFICATION

1. BUILDING NAME(S): Hauppauge "Village Hall"
2. COUNTY: Suffolk TOWN/CITY: Islip VILLAGE: Hauppauge
3. STREET LOCATION: Intersection of Veteran's Memorial Hwy. & Town Line Rd.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: _____ ADDRESS: _____
6. USE: Original: village hall Present: meeting hall
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain by app't.

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints ☐
(if known) b. wood frame with light members ☒
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO: Neg. KK XVI-7, fm. NE

13. MAP: NYS DOT Central Islip Quad



HP-1



- 1A 6
14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☒
 d. developers ☐ e. deterioration ☐
 f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn ☐ b. carriage house ☐ c. garage ☐
 d. privy ☐ e. shed ☐ f. greenhouse ☐
 g. shop ☐ h. gardens ☐
 i. landscape features: _____
 j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land ☐ b. woodland ☐
 c. scattered buildings ☐
 d. densely built-up ☐ e. commercial ☒
 f. industrial ☐ g. residential ☒
 h. other: major roadway interchange

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

The Hauppauge Village Hall is a long, rectangular, one story, gable roof building with variegated cladding in the peaks. It is located at a major highway interchange.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
 Refer to 1980 Inventory Form

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1887

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:


This building is the meeting hall for local social events, the Methodist Church Women's Auxiliary, the PTA, the Suffolk County Farm Bureau and Home Bureau, and the Hauppauge Men's Club.

Refer to 1980 Inventory Form.

21. SOURCES:
 Marr, Jack. History of Hauppauge, Long Island, 1981. (edited edition)
Smithtown News, 6/30/1977.

22. THEME:

Research by the Society for the Preservation of Long Island Antiquities - KEK



Hauppauge in 1902, from a survey by E. Belcher Hyde. (Courtesy Richard H. Handley collection, Long Island Room, Smithsonian Library)

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR O
UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Town of Smithtown DATE: May 15, 1980
99 West Main Street
YOUR ADDRESS: Smithtown, NY 11787 TELEPHONE: (516) 360-7540
ORGANIZATION (if any): Town of Smithtown

IDENTIFICATION

1. BUILDING NAME(S): Hauppauge Village Hall
2. COUNTY: Suffolk TOWN/CITY: Smithtown * VILLAGE: Hauppauge
3. STREET LOCATION: Veteran's Memorial Highway
4. OWNERSHIP: a. public ☒ b. private ☐
5. PRESENT OWNER: Haup. Village Hall ASSN ADDRESS: _____
6. USE: Original: meeting hall Present: meeting hall
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain _____

*Islip

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints ☐
(if known) b. wood frame with light members ☒
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known):
1920: Attic lowered, eliminating second floor.

12. PHOTO:

NJM-1.13

13. MAP:

DOT, Central Islip Quad

