## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

UNIQUE SITE NO. 03-05-0560-1550 Sa 29
UNIQUE SITE NO. 03-05-0560-155 QUAD
QUAD ()
QUAD ()
QUAD ()
일 회사회장 중요 전 전 전 전 보이 있는 것이다. 그는 것이 나는 그는 것이 되는 것이다. 그리고 있는 것이다. 그는 것이다. 그리고 있는 것이다.
SERIES
NEG. NO. green

YOUR NAME:	Town o	f Isl	in – Towr	ı H <b>all</b> DA	TE: 7/24	1/79
VOUD ADDDESS	655		Street			laali kliko


ORGANIZATION (if any): Department of Planning and Development

I. BUILDING NAM	E(S): Robert Nunn	s House	
			VILLAGE: Sayville
	ION: <u>221 Handsome</u>		
4. OWNERSHIP:	a. public 🗆 🐧 private	£X	
	R: Alan Ianell		see:#3 above
	residence		
	TO PUBLIC: Exterior vis		
	Interior ac	cessible: Explain	
<u>DESCRIPTION</u>	보면 하는 것으로 있는 것이 있는 것이 없는 것이 없다면 함께 함께 있다. 하는 것이 하는 것은 것이 하는 것이 되었습니다. 그는 것은 것이 없는 것이 없는 것이 없다.		
8. BUILDING	a. clapboard 🔲 'b. ste	one 🗆 💢 c. brick	🔲 d. board and batten 🔲
			어머니 (1985년 1985년 1985년 1985년 - 1985년 1987년 1987년 1987년 1987년 - 1987년 1987년 1987년 1987년 1987년 1987년 1987년 1987년
MATERIAL:	e. cobblestone 🔲 f. sh	ingles 🔀 🛮 g. stucc	o □ ∴ other:
MATERIAL:	e. cobblestone 니 f. sh	ingles 🔀 🛚 g. stucc	ø □ other:
	a. wood frame with inter	locking joints [	
	a. wood frame with inter	locking joints	
9. STRUCTURAL	a. wood frame with inter b. wood frame with light c. masonry load bearing	tocking joints  members  walls	
9. STRUCTURAL SYSTEM: (if known)	a. wood frame with inter b. wood frame with light c. masonry load bearing	tocking joints  members  walls	
9. STRUCTURAL SYSTEM:	a. wood frame with inter b. wood frame with light c. masonry load bearing d. metal (explain)	Hocking joints [] t members [ <b>x</b> ] walls [] : 0 0 = 7	
9. STRUCTURAL SYSTEM: (if known)	a. wood frame with inter b. wood frame with light c. masonry load bearing d. metal (explain)	Hocking joints (	
9. STRUCTURAL SYSTEM: (if known)	a. wood frame with inter b. wood frame with light c. masonry load bearing of metal (explain) e. other	tocking joints () t members (x) walls () c. fair ()	d. deteriorated $\Box$

12. PHOTO: NJM-5, neg. 3

13. MAP: Bowe-Anderson





14.	THREATS TO BUILDING: a. none known ₩ b. zoning □ c. roads □ d. developers □ e. deterioration □
15.	f. other:  RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house c. garage   d. privy c. shed c., f. greenhouse   g. shop h. gardens
16.	i. landscape features: j. other:  SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land  b. woodland co. scattered buildings co. scattered buildings co. densely built-up  e. commercial  f. industrial g. residential  co. h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
Th be	(Indicate if building or structure is in an historic district)  e Nunns House is located on the east side of Handsome Avenue, tween Jones Drive and Elm Street.
3 co wr fi mu	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): story, unaltered, Queen Anne Style, multigabled house, completely vered with original decorative shingles. Original tower and aparound porch with turned posts and wooden spandrels. Five replaces, Oriel windows in peak of front gable, Queen Anne lti-paned windows.  NIFICANCE DATE OF INITIAL CONSTRUCTION: prior to 1888
	ARCHITECT:  BUILDER:
Th fo: sh	HISTORICAL AND ARCHITECTURAL IMPORTANCE: is house, owned by Robert Nunns in 1915, is of particular walue r its striking architectural features, such as its decorative ingling, tower, and Queen Anne detailing. It is especially teworthy that this house stands virtually unaltered.
E.	SOURCES: Belcher Hyde, <u>Atlas of a Part of Suffolk County, Long Island</u> New York, South Shore, Brooklyn: 1915. 88 Map from the endpapers of: Charles G. Stevenson, But as Yes-

22. THEME: terday, a History of St. Ann's Church, Sayville, 1967.
Prepared by: Society for the Preservation of Long Island Antiquities
Setauket, New York 11733
Nina Monastero, Research Assistant
July, 1979