BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OI	FICE USE ONLY
UNIQUI	E SITE NO. <u>10305,000 & 5.5</u>
OUAD_	
SERIES	
NEG. N	0

YOUR NAME:	Town o	f Isli	p/SPLI	Α	DATE	May 1990	
	Town H	all, 6	55 Mai	n St.	7		15.0
YOUR ADDRESS:	Islip,	L.I.,	N.Y.	11751	_TELEPHON	_{IE:} 516,224,5450	
ORGANIZATION (if anv):	Dept.	of Pl	anning,	Housing,	and Development	
				1			


<u>IDENTIFICATION</u>	
1. BUILDING NAME	(S): 1½ story House
2. COUNTY: Suf	folk TOWN/CITY: Islip VILLAGE: Sayville
3. STREET LOCATI	ON: 275 Lincoln Ave.
4. OWNERSHIP:	a. public 🗀 b. private 🗵
5. PRESENT OWNER	residence Present: residence
6. USE: Original:	residence Present: residence
7. ACCESSIBILITY	TO PUBLIC: Exterior visible from public road: Yes No Interior accessible: Explain
<u>DESCRIPTION</u>	
8. BUILDING	a. clapboard \square b. stone \square c. brick \square d. board and batten \square
MATERIAL:	e. cobblestone f. shingles g. stucco other: modern siding
9. STRUCTURAL	a. wood frame with interlocking joints □
SYSTEM:	b. wood frame with light members [? needs framing inspection
(if known)	있는 사용하는 동물에 들고 사용을 가게 된다면 한다면 하면 하면 사용을 가면 하는 것이다. 그는 사용을 하면 사용을 하는 것이다면 하는 것이다면 하는데 다른 것이다. 그는 사용을 다 하는데 다른 사
	d. metal (explain)
	e, other
0. CONDITION: 4	i. excellent 🕱 b. good 🗆 c. fair 🔲 d. deteriorated 🗔
	i. original site 🗷 b. moved 🔲 if so,when?
1. INTEGRITY: 3	


modern siding added

12. PHOTO: Neg. KK XXIV-2, fm. NW

13. MAP:

NYS DOT composite Patchogue/Sayville Quads





15. RELATED OUTBUILDINGS AND PROPERTY:	14.	THREATS TO BUILDING: a. none known \(\mathbb{X} \) b. zoning \(\mathbb{C} \) c. roads \(\mathbb{C} \) d. developers \(\mathbb{C} \) e. deterioration \(\mathbb{C} \)
a open industrial □ c. scattered buildings □ d. densely built-up □ e. commercial □ f. industrial □ g. residential ☑ h. other: 17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district) 275 Lincoln Avenue is located on the east side of the street among residences of similiar and later date. Several examples of this type stand in the vicinity. 18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): 275 Lincoln Avenue is a 1½ story, three bay, center entrance plan, gable roof house with a shed roof extension on the rear (east). The upper story contains two large under-eave windows on the main (west) facade. A gable roof porch with scalloped infill covers the entrance. SIGNIFICANCE 19. DATE OF INITIAL CONSTRUCTION:		RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage c.
(Indicate if building or structure is in an historic district) 275 Lincoln Avenue is located on the east side of the street among residences of similiar and later date. Several examples of this type stand in the vicinity. 18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): 275 Lincoln Avenue is a 1½ story, three bay, center entrance plan, gable roof house with a shed roof extension on the rear (east). The upper story contains two large under-eave windows on the main (west) facade. A gable roof porch with scalloped infill covers the entrance. SIGNIFICANCE 19. DATE OF INITIAL CONSTRUCTION: Mid 19th century ARCHITECT: BUILDER: 20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 275 Lincoln Avenue is a house type that would generally be considered to date from the mid 19th century. Furthur inspectiona nd research is needed to determine the exact date.	16.	a open land □ 0. Woodland □ c. scattered buildings □ d. densely built-up □ e. commercial □ f. industrial □ g. residential ☒
of similiar and later date. Several examples of this type stand in the vicinity. 18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): 275 Lincoln Avenue is a 1½ story, three bay, center entrance plan, gable roof house with a shed roof extension on the rear (east). The upper story contains two large under—eave windows on the main (west) facade. A gable roof porch with scalloped infill covers the entrance. SIGNIFICANCE 19. DATE OF INITIAL CONSTRUCTION:	17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
275 Lincoln Avenue is a 1½ story, three bay, center entrance plan, gable roof house with a shed roof extension on the rear (east). The upper story contains two large under-eave windows on the main (west) facade. A gable roof porch with scalloped infill covers the entrance. SIGNIFICANCE 19. DATE OF INITIAL CONSTRUCTION: Mid 19th century ARCHITECT: BUILDER: 20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 275 Lincoln Avenue is a house type that would generally be considered to date from the mid 19th century. Furthur inspectiona nd research is needed to determine the exact date.		of similiar and later date. Several examples of this type stand in the
275 Lincoln Avenue is a 1½ story, three bay, center entrance plan, gable roof house with a shed roof extension on the rear (east). The upper story contains two large under-eave windows on the main (west) facade. A gable roof porch with scalloped infill covers the entrance. SIGNIFICANCE 19. DATE OF INITIAL CONSTRUCTION: Mid 19th century ARCHITECT: BUILDER: 20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 275 Lincoln Avenue is a house type that would generally be considered to date from the mid 19th century. Furthur inspectiona nd research is needed to determine the exact date.	18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
ARCHITECT: BUILDER: 20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 275 Lincoln Avenue is a house type that would generally be considered to date from the mid 19th century. Furthur inspectiona nd research is needed to determine the exact date.		275 Lincoln Avenue is a $1\frac{1}{2}$ story, three bay, center entrance plan, gable roof house with a shed roof extension on the rear (east). The upper story contains two large under-eave windows on the main (west) facade. A gable
BUILDER: 20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 275 Lincoln Avenue is a house type that would generally be considered to date from the mid 19th century. Furthur inspectiona nd research is needed to determine the exact date.	SIG 19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: Mid 19th century
BUILDER: 20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 275 Lincoln Avenue is a house type that would generally be considered to date from the mid 19th century. Furthur inspectiona nd research is needed to determine the exact date.		ARCHITECT:
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 275 Lincoln Avenue is a house type that would generally be considered to date from the mid 19th century. Furthur inspectiona nd research is needed to determine the exact date.		
to date from the mid 19th century. Furthur inspectiona nd research is needed to determine the exact date. 21. SOURCES:	20.	
. 기업하는 그는 2015년 전략 전략적인 내가면 외향 전문이 가장 모든 하는데 그는 그는 그는 사람들은 중요한 경험에 들어 들어 그는 그 그는 그로 생활을 위해 가장 하는데 어떻게 되었다.		to date from the mid 19th century. Furthur inspectiona nd research is
. 기업하는 10명 (20명) 전환경 시작하는 1일 중인 10명 (20명) 10명 - 10명 - 10명 (20명) 10명 - 1		
E. Belcher Hyde. Atlas of the Ocean Shore of Suffolk County, L.I. (westerly	21	하다 마음 가게 못했습니다. 내가 하는데 나는데 하는데 나는데 그 나는데 그는데 그는데 그를 가는데 하는데 하는데 하는데 그는데 그는데 가게 바로 하는데 가게 되었다.

22. THEME: Research by Society for the Preservation of Long Island Antiquities - KEK

section), 1902.