BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR O	FFICE USE (ONLY	
UNIQU	E SITE NO.	0305.0	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
OUAD			
SERIES			
NEG. N			

WS 1

YOUR NAME:	Town of Islip/SPLIA DATE. May 1990	
	Town Hall, 655 Main St.	For the second
YOUR ADDRESS:_	Islip, L.I., N.Y. 11751 TELEPHONE: 516.224.5450	

ORGANIZATION (if any): Dept. of Planning, Housing, and Development **IDENTIFICATION** 1. BUILDING NAME(S): Van Wyen House
2. COUNTY: Suffolk TOWN/CITY: _____
3. STREET LOCATION: 35 West Avenue Islip VILLAGE: West Sayville 7. ACCESSIBILITY TO PUBLIC. Exterior visible from public road. Yes 🗷 No 🗀 Interior accessible: Explain ___private residence DESCRIPTION a. clapboard

b. stone

c. brick

d. board and batten

e. cobblestone

f. shingles

g. stucco

other: b. stone

c. brick


d. board and batten 8. BUILDING MATERIAL: 9. STRUCTURAL a. wood frame with interlocking joints b. wood frame with light members K SYSTEM: c. masonry load bearing walls (if known) d. metal (explain) e. other a. excellent 🖈 b. good 🗆 c. fair 🗀 d. deteriorated 🗀 10. CONDITION: a. original site 🗷 b. moved 🗀 if so, when? 11. INTEGRITY: c. list major alterations and dates (if known):

12. PHOTO: Neg. KK XXIII-27, fm. W/NW

13. MAP:

NYS DOT composite Patchogue and Sayville Quads






14.	THREATS TO BUILDING: a, none known ☑ b. zoning □ c. roads □ d. developers □ e. deterioration □
	if: other
15.	사고에 가고 먹다면 된 그는 그는 이 가는 그는 것을 하고 있다. 그래 하는 사람들은 그래 가는 사람들이 되었습니다. 그는 사람들이 되었습니다. 그는
	a, barn□ b, carriage house □ c. garage □ d. privy □ e, shed □ f. greenhouse □
	g. shop h. gardens
	i. landscape features: Large tree in front yard
	i. other: matching others on street in size and type.
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):
	a. open land 🗆 b. woodland 🗔
	c. scattered buildings 🔲
	d. densely built-up 🗔 e. commercial 🗆
	f. industrial 🔲 g. residential 🔯
	h.other: <u>Suffolk Cnty. Park and Marine Museum to w</u> est.
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
	35 West Avenue, restored in 1988/89, is located on the east side of the street among similiar residences that line the road opposite the County Park on the west side. These houses are equally spaced and set back from West Avenue at similiar distances.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
	35 West Avenue is a $1\frac{1}{2}$ story, three bay, side entrance plan, gable
	roof house set perpendicular to the street. A two bay, smaller wing is attached on the south. Both units are fronted by a porch with Tuscan columns. The principle gable peak features stick-work at the
	apex.
SIG	NIFICANCE DATE OF INITIAL CONSTRUCTION: 1898
19.	DATE OF INITIAL CONSTRUCTION: 1898
	ARCHITECT:
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
	The Van Wyen House is a well-restored example of a West Sayville bayman's house. This row of baymen's houses is of local significance.
	CANTON NEW TOTAL CONTROL OF THE CON THE SECOND CONTROL OF THE CONTROL O
21.	SOURCES:
	하다는 하는 사람들은 얼마를 가면 하는 것이 되었다. 그는 사람들은 얼마는 그는 사람들은 얼마를 하는 것이다.
	Correspondence, John Ernest, 35 West Avenue, West Sayville.
	THEME:
	Research by Society for the Preservation of Long Island Antiquities - KEK



Van Wyen House, c. 1920.



Neg. KK XXIII-26, fm. NW, view of streetscape with Van Wyen House at center.



1988 photograph of east facade of Van Wyens House, Coll. John & Mary Ernest.